


# DELIVERY NOTE WP

**DELIVER TO :**

GALAXY AEROSPACE (M) SDN. BHD.  
CAMO DEPARTMENT  
Lot 11, MRO Centre,  
Malaysia International Aerospace Centre,  
Sultan Abdul Aziz Shah Airport,  
47200 Subang, Selangor  
Malaysia.  
Attn : Zaty Nadhira binti Mohamed Zuhari

**DN NUMBER : GAM/DN/BOC/21-243**  
**OUR REFERENCE : 9M-BOC-8898**  
**WO REFERENCE : 2021-8898**  
**DATE COMPLETION: 6 DECEMBER 2021**  
**AJL NUMBER : 04481**

A/C DETAILS							
A/C TYPE	AW139	A/C REG	9M-BOC	A/C S/N	31289		
OWNER / OPERATOR	FIRE AND RESCUE DEPT. OF MALAYSIA	A/C TOTAL TIME	3324:02	LANDINGS	5834		
ENGINE #1 S/N	PCE-KB0661	T.S.N	3324:02	T.S.O	-		
ENGINE #2 S/N	PCE-KB0659	T.S.N	3324:02	T.S.O	-		
LIST OF TASK PERFORMED	WP NUMBER	NUMBER OF PAGES					
		*WS	*PR	*ARC	*S	*SBC	*OTH
SB139-686 PART I	001	1	1	-	-	1	-
*THIS IS TO CERTIFY THAT TASKS LISTED ABOVE HAS BEEN ACCOMPLISHED AS PER PO/WORK ORDER/SERVICE ORDER NO. AS ABOVE.							
NAME	NURUL LYANA MUHAMAD	SIGNATURE		DATE	29 DECEMBER 2021		
VERIFIED AND ACCEPTED BY				MUHAMMAD IHSAN MASRI CAMO Planner Galaxy Aerospace (M) Sdn. Bhd. (1040262-D)			
DATE				03 JAN 2022			

- \*WS – WORKSHEET
- \*PR – PART REPORT
- \*ARC – AUTHORISED RELEASE CERTIFICATE
- \*S – SERVICEABLE LABEL
- \*SBC – SERVICE BULLETIN COMPLIANCE
- \*OTH – OTHERS

# WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

**Address:** Lot 11-14, MRO Centre, Malaysia  
International Aerospace Centre, SAAS Airport,  
Subang  
Malaysia

**Attention:** Mr. Syafrul Yamani  
Engineering Manager  
syafrul@galaxyaerospace.my

**Work Order Number:** 2021-8898

**Work Pack Reference:** 9M-BOC-8898

**Date Issued:** 24/11/2021

**A/C Registration / SN:** 9M-BOC/31289

**Sheet:** 1 of 1

**Description:**

Item	Description/Task/Inspection	Reference	Man Hours
1	ASB NO. 139-686, NEW ISSUE PART I (EASA AD 2021-0259) ATA 53 - TAIL GEAR BOX FITTING INSPECTION  <i>Due at 3339:37 FH</i>	ASB NO. 139-686, NEW ISSUE PART I	<u>2.0</u> (PLEASE ADVISE)

**Remark/Notes:**

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.  
Best Regards,

Zaty Nadhira Mohamed Zuhari  
Continuing Airworthiness Management Manager  
Email: zaty@galaxyaerospace.my









CLIENT/OWNER: FIRE AND RESCUE DEPT. OF MALAYSIA AIRCRAFT TYPE: AW139 REGISTRATION: 9M-BOC BASE/FACILITY: <b>MIRA</b> DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO: 8898-001
	AIRCRAFT	31289	REFER WORKPACK		WORK/INSP/DESC: ASB NO.139-686 PART I
	#1 ENGINE:	PCE-KB0661	REFER WORKPACK		WORKPACK REF: 9M-BOC-8898
	#2 ENGINE:	PCE-KB0659	REFER WORKPACK		AJL REF NO.: REFER WORKPACK
			NG / N1	NF / N2	SHEET: 1 OF 1

Reason for raising: ASB NO. 139-686, NEW ISSUE PART I (EASA AD 2021-0259) ATA 53 - TAIL GEAR BOX FITTING INSPECTION TO BE CARRIED OUT IN ACCORDANCE WITH JBPM/CAMO/AMP/AW139 ISSUE 02 REVISION 01 AW139 IETP - 39TH ISSUE: 2021-06-07 UPDATED: 2021-07-20 OR LATEST APPROVED REVISIONS ATA 53 - TAIL GEAR BOX FITTING INSPECTION	Raised by and date: Muhammad Ihsan Masri 24/11/2021	Other requirements/information: NIL
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------	----------------------------------------

Item	Description	Technician	* Eng. CRS	Date
1	ASB NO. 139-686, NEW ISSUE PART I (EASA AD 2021-0259) ATA 53 - TAIL GEAR BOX FITTING INSPECTION TO BE CARRIED OUT IN ACCORDANCE WITH ASB NO. 139-686, NEW ISSUE PART I COMPLIANCE INSTRUCTIONS  REFERENCE: ASB NO. 139-686, NEW ISSUE PART I  REMARKS: C/O FOUND SATIS.	<i>Mud.</i>	 	6/12/2021

\*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

\*The work recorded above has been carried out in accordance with the requirements of the \_\_\_\_\_ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK ✓ WHERE APPLICABLE

PARTS LABELLED & RETURNED	LOG RAISED	DUPLICATE INSP.	GROUND RUN	FLIGHT TEST	TORQUE CHK.	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	D/E STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	DEM/COMP LOG CARD	MOD RECORD BOOK
---------------------------	------------	-----------------	------------	-------------	-------------	----------------------	------------------	-------------------	--------------	---------------	------------	-------------------	-----------------	--------------------	----------	-------------------	-----------------

Please send to the following address:  <b>LEONARDO S.p.A.</b> <b>CUSTOMER SUPPORT &amp; SERVICES - ITALY</b>  <b>PRODUCT SUPPORT ENGINEERING &amp; LICENSES DEPT.</b> Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988	<b>SERVICE BULLETIN COMPLIANCE FORM</b>	Date: 6/12/2021
	Number: <b>ASB NO. 139-686, NEW ISSUE PART I</b>	
Revision: -		

Customer Name and Address: <b>GALAXY AEROSPACE (M) SDN BHD</b> <b>(GADING GROUP OF COMPANIES)</b> Suite 11-14, Helicopter Centre, <b>GALAXY AEROSPACE (M) SDN BHD</b> Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, <b>SELANGOR DARUL EHSAN</b>	Telephone: <b>603-7734 7226</b>
	Fax: <b>603-7734 7226</b>
	B.T. Compliance Date:

Helicopter Model	S/N	Total Number	Total Hours	T.S.O.
AW139	31289	1	3324:02	

Remarks:

Information:

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.



CLIENT/OWNER: FIRE AND RESCUE DEPT. OF MALAYSIA	SERIAL NO. 31289	HOURS	LDG/CYCLE	WORKSHEET NO: 8898-001
AIRCRAFT TYPE: AW139	AIRCRAFT	REFER WORKPACK		WORK/INSP/DESC: ASB NO.139-686 PART I
REGISTRATION: 9M-BOC	#1 ENGINE: PCE-KB0661	REFER WORKPACK		WORKPACK REF: 9M-BOC-8898
BASE/FACILITY:	#2 ENGINE: PCE-KB0659	REFER WORKPACK		AJL REF NO.: REFER WORKPACK
DATE IN: REFER WORKPACK OUT: REFER WORKPACK			NG / N1	NF / N2
				SHEET: 1 OF 1

REASON FOR RAISING: ASB NO. 139-686, NEW ISSUE PART I (EASA AD 2021-0259) ATA 53 - TAIL GEAR BOX FITTING INSPECTION TO BE CARRIED OUT IN ACCORDANCE WITH JBPM/CAMO/AMP/AW139 ISSUE 02 REVISION 01 AW139 IETP - 39TH ISSUE: 2021-06-07 UPDATED: 2021-07-20 OR LATEST APPROVED REVISIONS	Raised by and date: Muhammad Ihsan Masri 24/11/2021	Other requirements/information: NIL
-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------	----------------------------------------

Item	Part No	Description	Serial Number		Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX	Release Reference
			Off	On					
(Table content is crossed out with a diagonal line)									

NAME	FIRM	SIGN & APPROVAL	DATE
HARIS	GAM		6/12/2021

\*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

\*The work recorded above has been carried out in accordance with the requirements of the \_\_\_\_\_ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK ✓ WHERE APPLICABLE

PARTS LABELED & RETURNED	D/D RAISED	DUPLICATE INSP	GROUND RUN	FLIGHT TEST	TROUBLE CHR	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	D/D STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	COM/COMP LOG CARD	MOD RECORD BOOK
--------------------------	------------	----------------	------------	-------------	-------------	----------------------	------------------	-------------------	--------------	---------------	------------	-------------------	-----------------	--------------------	----------	-------------------	-----------------