


DELIVERY NOTE WP

DELIVER TO :

GALAXY AEROSPACE (M) SDN. BHD.
CAMO DEPARTMENT
Lot 11, MRO Centre,
Malaysia International Aerospace Centre,
Sultan Abdul Aziz Shah Airport,
47200 Subang, Selangor
Malaysia.
Attn : Zaty Nadhira binti Mohamed Zuhari

DN NUMBER : GAM/DN/BOD/23-085
OUR REFERENCE : 9M-BOD-15573
WO REFERENCE : 2023-15573
DATE COMPLETION: 19 May 2023
AJL NUMBER : 05050

A/C DETAILS								
A/C TYPE	AW139	A/C REG	9M-BOD	A/C S/N	31291			
OWNER / OPERATOR	FIRE AND RESCUE DEPT. OF MALAYSIA	A/C TOTAL TIME	3637:43	LANDINGS	7069			
ENGINE #1 S/N	PCE-KB0674	T.S.N	3637:43	T.S.O	-			
ENGINE #2 S/N	PCE-KB0658	T.S.N	3637:43	T.S.O	-			
LIST OF TASKS PERFORMED	WP NUMBER	NUMBER OF PAGES						
		*WS	*PR	*TR	*ARC	*S	*SBC	*OTH
SB139-754 PART III	001	1	1	1	-	-	1	5
*THIS IS TO CERTIFY THAT TASKS LISTED ABOVE HAS BEEN ACCOMPLISHED AS PER PO/WORK ORDER/SERVICE ORDER NO. AS ABOVE.								
NAME	ROSE AZREENNA ROSLEE	SIGNATURE		DATE	19 MAY 2023			
VERIFIED AND ACCEPTED BY				NUR HUSNINA BINTI MUHAMAD ZURAJDI CAMO Planner Galaxy Aerospace (M) Sdn Bhd (1040262-D)				
DATE				19/05/2023				

- *WS – WORKSHEET
- *PR – PART REPORT
- *ARC – AUTHORISED RELEASE CERTIFICATE
- *S – SERVICEABLE LABEL
- *SBC – SERVICE BULLETIN COMPLIANCE
- *OTH – OTHERS

WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

<p>Address: Lot 11-14, MRO Centre, Malaysia International Aerospace Centre, SAAS Airport, Subang Malaysia</p> <p>Attention: Mr. Syafrul Yamani Engineering Manager syafrul@galaxyaerospace.my</p>	<p>Work Order Number: 2023-15573</p> <p>Work Pack Reference: 9M-BOD-15573</p> <p>Date Issued: 09/05/2023</p> <p>A/C Registration / SN: 9M-BOD/31291</p> <p>Sheet: 1 of 1</p>
---	---

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	EASA AD 2023-0071 PARA (3) (EASB 139-754 PART III) - ATA 62 MAIN ROTOR (MR) PITCH LINK UPPER ROD END ASSY INSPECTION	EASA AD 2023-0071 PARA (3) (EASB 139-754 PART III)	<u>1.0</u> (PLEASE ADVISE)
	<i>DUE AT 3641:07 FH</i>		

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.
Best Regards,



Zaty Nadhira Mohamed Zuhari
Continuing Airworthiness Management Manager
Email: zaty@galaxyaerospace.my



CLIENT/OWNER: JABATAN BOMBA DAN PENYELAMAT MALAYSIA	SERIAL NO.	HOURS	LDG/CYCLE	WORKPACK NO: 9M-BOD-15573
AIRCRAFT TYPE: AW139	AIRCRAFT 31291	3637:43	7069	WORK/INSP/DESC: EASA AD 2023-0071 PARA
REGISTRATION: 9M-BOD	#1 ENGINE: PCE-KB0674	3637:43	-	AERONET JOB NO.: 2023-15573
BASE/FACILITY: BERTAM	#2 ENGINE: PCE-KB0658	3637:43	-	AJL REF NO.: REFER WORKPACK
DATE IN: 19/5/23 OUT: 19/5/23			NG / N1	NF / N2
				SHEET: 1 OF 1



Reason for raising: **EASB 139-754 PART III - ATA 62 - MAIN ROTOR (MR) PITCH LINK UPPER ROD END ASSY INSPECTION TO BE CARRIED OUT I.A.W. AW139 IETP 42nd ISSUE 2022-12-01 REV. 02 UPDATED 2023-02-28 TO THE ALL-LATEST ISSUE/REVISION/UPDATES. EMM PT6C-67C ISSUE NO. 30.0 DATED 20-03-2023. AMP NO. JBPM/CAMO/AMP/AW139 ISSUE 2 REV. 1**

Raised by and date: **CAMO; Husnina 09/05/2023**

Other requirements/information: **NIL**

List of scheduled inspection and all work carried out under this workpack including individual reference			DATE INSPECTION COMPLETED	Master Signature Schedule		
NO.	INSPECTION / WORK	WORKSHEET REF		NAME	SIGNATURE	APP/STAMP
1	EASA AD 2023-0071 PARA (3) (EASB 139-754 PART III) - ATA 62 MAIN ROTOR (MR) PITCH LINK UPPER ROD END ASSY INSPECTION	15573-001	19/5/2023	SYAHIDA	<i>Syahida</i>	
<p>Galaxy Aerospace (M) Sdn. Bhd.</p> <p>I hereby certify the following task has been performed and found satisfactory.</p> <p>1) All the tools and equipment used for maintenance has been removed from the aircraft. 2) All the access panels removed for maintenance are correctly reinstalled. 3) All the excess spares and materials have been returned to the CAMO Planner for return plan. 4) FOD check has been completed.</p> <p>Sign & Stamp: <i>Syahida</i> Date & Time: 19/5/23 0700</p>						

PART 145 - AMO RELEASE STATEMENT **AMO/2016/02**

THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND

* OEM PUBLICATION/REVISION AS PER REASON FOR RAISING ABOVE

* IF DIFFERENT FROM ABOVE. OEM PUBLICATION/REVISION.....

* TICK ✓ WHERE APPLICABLE


NAME	SYAHIDA
SIGN & APPROVAL	<i>Syahida</i>
FIRM	GAM
DATE	19/5/2023

PART M - CAMO ACCEPTANCE STATEMENT

THIS IS TO CERTIFY THAT THE ABOVE MENTIONED WORK PACKAGE HAS BEEN REVIEWED, CHECKED FOR COMPLETION AND UPDATED IN THE MAINTENANCE SOFTWARE.

NUR HUSNINA BINTI MUHAMMAD ZURAIDI

NAME	SIGN & APPROVAL	DATE
	<i>Husnina</i>	26/05/23

Please send to the following address: LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988	SERVICE BULLETIN COMPLIANCE FORM	Date: 19/5/2023 <i>Sy</i> 31/3/2023
Number: EASA AD 2023-0071 PARA (3) CEASB (39-754 PART III)		
Revision: -		


Customer Name and Address: GALAXY AEROSPACE (M) SDN. BHD. SUITE 11-14, HELICOPTER CENTRE, MALAYSIA INTERNATIONAL AEROSPACE CENTRE, SULTAN ABDUL AZIZ SHAH AIRPORT, 47200, SUBANG, SELANGOR.	Telephone: 603-7734 7226
	Fax: 603-7734 7226
	B.T. Compliance Date: 19/5/2023

Helicopter Model	S/N	Total Number	Total Hours	T.S.O.
AW-139	31291	-	3637:43	-

Remarks:

CARRIED OUT FOUND SATISFACTORY

Sy
 19/5/2023






Information:

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.



Aircraft Serial No:	31291	Work Pack No:	9M-BOD-15573
Aircraft Type:	AW139	DESC:	EASB 139-754 PART III -
Aircraft Reg:	9M-BOD	PAGE:	1 Of 1

Description	Part No	Serial Number	Worksheet Ref No. / Item No.	Calibration Due Date
 				



REFER 9M-300-15573 , ITEM 1


MR BLADE (WHITE)

S/N : MCR 9391

Sybil



19/5/2023




REFER 9M-BOD-15573, ITEM 1

MR BLADE (ORANGE)

S/N: MCR 9394

Sybil
19/5/23





REFER 9M-800-15573, ITEM 1

MR BLADE (BLUE)

SN: MCR 9393

Sybil
19/5/23






REFER 9M-600-15573, ITEM 1


MR BLADE (RED)

SN: ~~CM~~ MCR 9292


SN 191573

19/5/2023



REFER 9M-800-15573, ITEM 1.

MR BLADE (BLACK)

S/N: MCR 9390

Sybil



19/5/2023



SB 139-754 Rev. / – Inspection Report		
Date	19/5/2023	
Upper Rod End Assy P/N 3G6230A01133	S/N	FH
	mcr 9390, mcr 9391, mcr 9394, mcr 9394, mcr 9292	
3637:43		
Installed on Helicopter <input checked="" type="checkbox"/>	Stock item <input type="checkbox"/>	
S/N	FH	Installed on Pitch Link Assy P/N 3G6230A01033 S/N (if applicable)
mcr 9390, mcr 9391, mcr 9393, mcr 9394, mcr 9292	3637:43	-
Dimension "X" measurement	N/A	
Notes: NOT   NOT APPLICABLE DUE TO ITEM KEPT IN STOCK IN WAREHOUSE.		

Figure 6