# **DELIVERY NOTE WP**



**DELIVER TO: \*AMENDED\*** 

GALAXY AEROSPACE (M) SDN. BHD.

CAMO DEPARTMENT

Lot 11, MRO Centre,

Malaysia International Aerospace Centre,

Sultan Abdul Aziz Shah Airport,

47200 Subang, Selangor

Malaysia.

Attn: Zaty Nadhira binti Mohamed Zuhari

DN NUMBER: GAM/DN/BOE/24/062

**OUR REFERENCE: 9M-BOE-18039** 

WO REFERENCE: 2023-18039

DATE COMPLETION: 03 JAN 2024

AJL NUMBER: 001556

				A/C	DETAILS					
A/C TYP	PE	AW	/189	A/C REG	910	1-BOE	Α/	c s/N	4	19045
OWNER			D RESCUE MALAYSIA	A/C TOTAL TIME	13	85:05	LAN	DINGS		2800
ENGINE #1	S/N	780	)235	T.S.N	12	14:27	Т	.s.o		-
ENGINE #2	S/N	780	)220	T.S.N	13	85:05	т	.s.o		-
LIST OF TA	SK PERI	FORMED	WP				BER OF PA			
			NUMBER	*WS	*PR	*TR	*ARC	*S	*SBC	*OTH
SB NO. 342- 001-UPDATE GENERATOR CONFIGURA	E OF GA		001	1	1	1	-	-	-	3
*THIS IS TO CE	ERTIFY T	HAT TASKS LI	STED ABOVE H	HAS BEEN ACCOMP	LISHED AS	PER PO/WO	ORK ORDER/S	ERVICE ORD	ER NO. 1AS A	BOVE.
NAME		NURUL AM	IRA	SIGNATUI	RE	h.		ATE		RUARY 2024
			VER	IFIED AND ACCE	PTED BY		Galaxy A	A BINTI MUHA AMO Planne erospace (M (1040262-D	) Sdn Bhd	
					DATE		27	02/20	24	
*****				*C CED\UCEA						

\*WS-WORKSHEET

\*S - SERVICEABLE LABEL

\*PR - PART REPORT

\*SBC - SERVICE BULLETIN COMPLIANCE

\*ARC – AUTHORISED RELEASE CERTIFICATE \*OTH – OTHERS

GAM/E-015 Page: 1



## **WORK PACKAGE HANDOVER**

43 7 5 5 6			
A/C REG :	9m - B0E	CHECK TYPE :	base maintnance
CHECK DUE :	ANNUAL CHECK	BASE :	miat

ITEM	DESCRIPTION	WORKPACK	WORKSHEET
1.	umc-80=-23-055		/
2.	9m-BOE-14857	/	/
3.	9m-80E-18039	/	<i>j</i>
4.	9M-BOE-15008	1	1
5.			
6.			
7.			
8.			
9.			
10.			

THIS CHECK PACKAGE IS HANDED OVER BY

NAME:

NUR HUSNINA BINT: MUHAMAD ZURAIDI

POSITION:

CAMO Planner Galaxy Aerospace (M) Sdn Bhd

ORGANIZATION:

(1040262-D)

20/02/2024

I HEREBY CONFIRM THE ACCEPTANCE OF THIS CHECK PACKAGE AND ITS CONTENT

NAME: NURUS AMIRA

POSITION: PPC

ORGANIZATION: GAM

DATE: 20/02/2024

NOTE: THIS FORM IS TO BE ATTACHED WITH THE WORK PACKAGE

# **DELIVERY NOTE WP**



## **DELIVER TO:**

GALAXY AEROSPACE (M) SDN. BHD.

CAMO DEPARTMENT

Lot 11, MRO Centre,

Malaysia International Aerospace Centre,

Sultan Abdul Aziz Shah Airport,

47200 Subang, Selangor

Malaysia.

Attn: Zaty Nadhira binti Mohamed Zuhari

DN NUMBER: GAM/DN/BOE/24/015

**OUR REFERENCE: 9M-BOE-18039** 

WO REFERENCE: 2023-18039

DATE COMPLETION: 03 JAN 2024

AJL NUMBER: 001556

				Α/	C DETAILS					
A/C TY	'PE	AW	/189	A/C REG	9N	1-BOE	Α/	C S/N		19045
OWNE		STATISTICS CONTROL OF THE	D RESCUE MALAYSIA	A/C TOTAL TIME	13	85:05	LAN	DINGS		2800
ENGINE #	1 S/N	780	0235	T.S.N	12	14:27	Т	.s.o		74
ENGINE #	2 S/N	780	)220	T.S.N	13	85:05	Т	.s.o		TE .
LIST OF TA	ASK PFR	FORMED	WP				BER OF PA			
			NUMBER	*WS	*PR	*TR	*ARC	*S	*SBC	*OTH
SB NO. 342 001-UPDAT GENERATO CONFIGURA	E OF GA		001	1	1	1	-	-	-	3
*THIS IS TO C	CERTIFY T	HAT TASKS LI	STED ABOVE F	HAS BEEN ACCON	1PLISHED AS	PER PO/W	ORK ORDER/S	ERVICE ORDE	R NO. 1AS	ABOVE.
NAME		NURUL AM	IRA	SIGNATU	JRE	Ps'	D	ATE	23 JAN	IUARY 2024
			VER	IFIED AND ACC	EPTED BY		Galaxy Aer	BINTI MUHAMA MO Planner ospace (M) S L040262-D)		
					DATE		23 J	AN 2024		
*****				** ***						

\*WS - WORKSHEET

\*S - SERVICEABLE LABEL

\*PR - PART REPORT

\*SBC - SERVICE BULLETIN COMPLIANCE

\*ARC – AUTHORISED RELEASE CERTIFICATE \*OTH – OTHERS



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.
Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my

## WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

Address: Lot 11-14, MRO Centre, Malaysia

International Aerospace Centre, SAAS Airport,

Subang Malaysia

Attention: Mr. Syafrul Yamani

Engineering Manager

svafrul@galaxvaerospace.mv

Work Order Number:

2023-18039

Work Pack Reference:

9M-BOE-18039

Date Issued:

22/12/2023

A/C Registration / SN:

9M-BOE/49045

Sheet:

of

Description:

Item Description/Task/Inspection

SB NO. 342-49-047, ISSUE 001 - UPDATE OF

GAS GENERATOR CONFIGURATION

Reference

SB NO. 342-49-047, ISSUE 001 DATED 27 APRIL 2023 Man Hours

1

(PLEASE ADVISE)

TO CARRIED OUT AS SOON AS POSSIBLE WITHOUT EFFECT ON REVENUE SERVICE

#### Remark/Notes:

- State this Work Order reference on your Work Package, Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
- 2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
- 3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
- 4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
- 5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
- 6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
- 7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you. Best Regards,

Zaty Nadhira Mohamed Zuhari

Continuing Airworthiness Management Manager

Email: zaty@galaxyaerospace.my



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

# WORKPACK

PENYELMAT MALAYSIA ARCARET TYPE. WYNTSS  ARCARET TYPE. WYNTSS  FILENINE: 780235   144; 23   -	OL IENIT	/OWNER: JABATAN BOMBA DAN		CEDIAL NO	HOURS	I DC/O	/CI =		MODRAGEN	). OM POE	19020
ABSOLATE TYPE AVISS REGISTRATION, SMECE REGISTRATION, SMECE REGISTRATION, SMECE REGISTRATION, SMECE REGISTRATION, SMECE RECISTRATION, SMECE RESISTRATION RECISTRATION R	CLIENT		AIDODAET					)			
REGISTRATION. SINCE RECENTION. IN AT 3 1-24 OUT 3 1-24  DATE IN 3 1-24 OUT 3 1-24  REPOSINE 780220 1385:05  REPOSINE 7802	AIRCRA	FT TYPE: AW189					Ī		+		
ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 10 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 20 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 20 P S / 24  ARE MAS AMOR RELAKS STATEMENT  NO / 20 P S / 24  ARE MAS AMOR RELAKS STATEMENT  AMO/ 2	REGIST	RATION: 9M-BOE	2001 0000000000000000000000000000000000					_	-		
Reason for raising:  SIN NO. 342-49-047, ISSUE 001 / UPDATE OF GAS GENERATOR CONFIGURATION  TO BE CAPHIED OUT I.A.W. SIN NO. 342-49-047, ISSUE 001 DATED 27 APRIL 2023  List of scheduled inspection and all work carried out under this workpack including individual reference  NO. INSPECTION / WORK  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATIO	BASE/F	ACILITY: WYAY	#2 ENGINE:	780220	1305.05			700-500		NO.	
SB NO. 342-49-047, ISSUE 001 / UPDATE OF GAS GENERATOR CONFIGURATION TO BE CARRIED OUT LAW. SB NO. 342-49-047, ISSUE 001 DATED 27 APRIL 2023  Liet of scheduled inspection and all work carried out under this workpack including individual reference  NO. INSPECTION / WORK  INSPECTION / WORK  WORKSHEET REF  OAS GENERATOR CONFIGURATION  ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  OAS GENERATOR CONFIGURATION  INSPECTION / WORK  WORKSHEET REF  INSPECTION / WORK  INSPECTION / W	DAIL III	. 51 -1 001.5 1 - 1								16 200 20	
Including Individual reference  NO. INSPECTION / WORK  1 SIS NO. 342-49-037, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SIS NO. 342-49-037, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  Molfp 2HAPIA  2 9162    Molfp 2HAPIA    Hereby certify the following task has been performed and found satisfactory:   1] All the tools and equipment used for maintenance has been removed from aincraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess panels and materials have been notified to AMO Planner for return plan.   4) FOD check has been plane.   Molfp 2HAPIA    Sign & Stamp:   Date & Time: 1600	SB NO.	342-49-047, ISSUE 001 // UPDATE OF				CAMÓ;	Husnir		Other requiren		on:
NO. INSPECTION / WORK WORKSHEET REF  1 SB NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  1 SB NO. 342-49-047, ISSUE 001 - UPDATE OF GAS GENERATOR CONFIGURATION  MOHD ZHAPIN  2 9162  Galaxy Aerospace (M) Sdn. Bhd.  I hereby certify the following task has been performed and found satisfactory:  1) All the tools and equipment used for maintenance has been removed from maintenance access has been reinstalled. 3) All the excess panels removed for maintenance access has been rotified to AMO Planner for return plan.  4) FOD check has been anotified to AMO Planner for return plan.  Sign & Stamp:  Date & Time: 1600	List	en antitat in a second and a second and a second and the second and the second and the second and the second a		under this wo	orkpack				Master Sig	ınature Schedu	le
GAS GENERATOR CONFIGURATION  3.1-2014  MoHD ZHAFIN  1862  MoHD ZHAFIN  1862  MoHD ZHAFIN  1862  MoHD ZHAFIN  1864  Silvar  Galaxy Aerospace (M) Sdn. Bhd.  I hereby certify the following task has been performed and found satisfactory:  1) All the tools and equipment used for maintenance has been removed from aircraft.  2) All the access penels removed for maintenance access has been reinstalled.  3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD back has been profes.  Sign & Stamp:  Date & Time: 1600	NO.	INSPECTION / WOR	RK	WORKSH	EET REF			NAME		SIGNATURE	APP/STAMP
Galaxy Aerospace (M) Sdn. Bhd.  Hereby certify the following task has been performed and found satisfactory:  1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been floge.  3.1.24  Sign & Stamp: Date & Time: 1600	1			18039	-001	3.1.20	24	WW.	Harrab	Sees	MO10 H
I hereby certify the following task has been performed and found satisfactory:  1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been lone.  3.1.24  Sign & Stamp: Date & Time: 1600			***************************************					Moto	2HAFIA	2	8162
I hereby certify the following task has been performed and found satisfactory:  1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been plane.  Sign & Stamp:  Date & Time: 1600											
I hereby certify the following task has been performed and found satisfactory:  1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been lone.  3.1.24  Sign & Stamp: Date & Time: 1600											
I hereby certify the following task has been performed and found satisfactory:  1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been plane.  Sign & Stamp:  Date & Time: 1600											
I hereby certify the following task has been performed and found satisfactory:  1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been plane.  Sign & Stamp:  Date & Time: 1600											
I hereby certify the following task has been performed and found satisfactory:  1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been plane.  Sign & Stamp:  Date & Time: 1600											
I hereby certify the following task has been performed and found satisfactory:  1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been plane.  Sign & Stamp:  Date & Time: 1600											
I hereby certify the following task has been performed and found satisfactory:  1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been plane.  Sign & Stamp:  Date & Time: 1600											
I hereby certify the following task has been performed and found satisfactory:  1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been plane.  Sign & Stamp:  Date & Time: 1600								SERVICE STATE OF THE SERVICE S			
I hereby certify the following task has been performed and found satisfactory:  1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been plane.  Sign & Stamp:  Date & Time: 1600	Г	Calavy Agrees	ace (M) Sdn	Bhd							
satisfactory:  1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been plane.  Sign & Stamp:  Date & Time: 1600					found						
removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been flone.  3.1.24  Sign & Stamp:  Date & Time: 1600		satisfactory:									
maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan.  4) FOD check has been flone.  3.1.24  Sign & Stamp: Date & Time: 1600  NAME		removed from aircraft. 2) All	the access par	nels removed	for						ell eller
4) FOD check has been flone.  3.1.24  Sign & Stamp: Date & Time: 1600  NAME  NAME		maintenance access has been re and materials have been notifie	installed. 3	) All the exce	ess spares						
ART 145 - AMO RELEASE STATEMENT  AMO/2016/02  NAME  NAME		4) FOD check has been flone.	e Qe								
ART 145 - AMO RELEASE STATEMENT		Sign & Stamp: MO1	Date	e & Time:	600						
ART 145 - AMO RELEASE STATEMENT	L										
ART 145 - AMO RELEASE STATEMENT											
HIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE		- AMO RELEASE STATEMENT		ECTED AND ACCO	OMPLISHED IN A	ACCORDANCE			NAME	MUHAM	MAD
ITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND  SIGN & APPROVAL	VITH CON	NTRACTED AMO EXPOSITION AND PROCE	DURE LATEST REV	ISION, AND	LIGHTLE HAP			SIG	N & APPROVAL	Men	3 (MO10)

PART M - CAMO ACCEPTANCE STATEMENT THIS IS TO CERTIFY THAT THE ABOVE MENTIONED WORK PACKAGE HAS BEEN REVIEWED, CHECKED FOR COMPLETION AND UPDATED IN THE MAINTENANCE SOFTWARE.

\* TICK ✓ WHERE APPLICABLE

NUR HUSNINA BINTI MUHAMAD ZURAIDI CAMO Planner

06/02 GAM/C-004 Rev 3 (01/22)

DATE

3.1.2024

Gam

SIGN & APPROVAL

FIRM

DATE

NAME



GALAXY AEROSPACE (M) SDN, BHD, [1040262-D]
Suite 17-14, Helicopter Centre, Malaysia International Aerospace Centre, Sulfan Aboul Aziz Shah Arport, 47200 Subang, Selangor Malaysia, Tel +603 7734 726 | Fax, +603 773-7556
www.galaxyaerospace.my | enquiry@galaxyaerospace.my WORKSHEET WORKSHEET NO: CLIENT/OWNER: JABATAN BOMBA DAN SERIAL NO. HOURS LDG/CYCLE 18039-001 PENYELAMAT MALAYSIA WORK/INSP/DESC: UPDATE OF GAS 49045 REFER WORKPACK **AIRCRAFT** AIRCRAFT TYPE: AW189 WORKPACK REF: 9M-BOF-18039 780235 REFER WORKPACK #1 ENGINE: REGISTRATION: 9M-BOE AJL REF NO .: REFER WORKPACK #2 ENGINE: 780220 REFER WORKPACK BASE/FACILITY: MIAT SHEET: 1 1 DATE IN: REFER WORKPACK OUT: REFER WORKPACK OF NG/N1 NF / N2 Reason for raising Raised by and date: Other requirements/information: SB NO. 342-49-047, ISSUE 001 // UPDATE OF GAS GENERATOR CONFIGURATION TO BE CARRIED CAMO; Husnina OUT I.A.W. SB NO. 342-49-047, ISSUE 001 DATED 27 APRIL 2023 22/12/2023 UPDATE OF GAS GENERATOR CONFIGURATION Technician \* Eng. CRS Description Date Item 1 SAFRAN SB 342-49-047 COMPLIANCE 3/1/2024 TITLE: UPDATE OF GAS GENERATOR CONFIGURATION TO CARRIED OUT THE PROCEDURE BY THE END USER OR MRO CENTER TO RETROFIT GAS GENERATOR P/N 341-01-11 INTO GAS GENERATOR P/N 341-01-12. NOTE: TECHNICAL RECORD TO UPDATE APU ENGINE LOG BOOK AND GAS GENERATOR LOG BOOK AS PER SB PROCEDURE PARA 3.1 STEP 1 & 2 NOTE: CAMO PLANNER TO UPDATE LATEST PART NUMBER IN CAMS REFERENCE: SAFRAN SERVICE BULLETIN 342-49-047 ISSUE NUMBER 001 DATED 27-APR-2023 REMARKS: CARRIED OUT . FOULD SATISFACTORY

*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malay the aircraft / aircraft component is considered ready for release to service.  *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with and in respect to that work the aircraft / aircraft component is considered ready for release to service.	sia Requirements a	and in respect to that	work
☐ TICK ✓ WHERE APPLICABLE			



GALAXY AEROSPACE (M) SDN, BHD, [1040262-D]
Sufe 11: 14, Helicopter Centro, Malays a International Aerospace Centre,
Sulfar Abdul Azir Shan Airport, 47200 Subang, Selangor, Malaysia,
Tel: +603.7734.726 [Fax: +603.7744.7566
www.galaxyaerospace.my | enquiry@galaxyaerospace.my

**PARTS REPORT** 

CLIENT/OWNER: JABATAN BOMBA DAN

PENYELAMAT MALAYSIA

AIRCRAFT TYPE: AW189 REGISTRATION: 9M-BOE

BASE/FACILITY: MIAT
DATE IN: REFER WORKPACK OUT: REFER WORKPACK

	SERIAL NO.	HOURS	LDG/CY	/CLE
AIRCRAFT	49045	REFER WO	RKPACK	
#1 ENGINE:	780235	REFER WO	RKPACK	
#2 ENGINE:	780220	REFER WO	RKPACK	
			NC / NH	NE / NO

WORKSHEET NO:

18039-001

WORKPACK REF:

WORK/INSP/DESC: UPDATE OF GAS 9M-BOE-18039

AJL REF NO .: SHEET:

REFER WORKPACK 1 OF

REASON FOR RAISING:

☐ TICK WHERE APPLICABLE

SETTL FILE

SB NO. 342-49-047, ISSUE 001 // UPDATE OF GAS GENERATOR CONFIGURATION TO BE CARRIED OUT I.A.W. SB NO. 342-49-047, ISSUE 001 DATED 27 APRIL 2023

Raised by and date: CAMO; Husnina 22/12/2023

NIL

Other requirements/information:

			Serial N	Number				Lifed Item Information	n. n.
1	Part No	Description	Off	On	Qty	Position	Reason	TSN/TSO/DUE/TIMEX	Release Reference
									-/
				u-Usu-Park wink					
AME	MUHA	^ ^ O	FIRM	am.		SIGN &	APPROVIA	MO10)	3.1.2024

Certifies that the work specified above, except as otherwise specified, was carried out in accordance with and in respect to that work the aircraft / aircraft component is considered ready for release to service.

7-111014-1

1.400.43

FLECHTEST

1,450.8

- LANDAR

(#1), MF

FILMET \*

FE: 6-11-E

11 ( K-, 14).



GALAXY AEROSPACE (M) SDN, BHD, [1040262-D]
Suite 11-14, Helcopter Centre, Malaysia International Aerospace Centre, Suitan Abdul Aziz Shan Airport, -7200 Subarg, Selanger, Malaysia, Tet +603 7737-7226 [ Fax: -603 7734 7826]
www.galaxyaerospace.iny | enquity@galaxyaerospace.iny

# **Tools Report**



Aircraft Serial No:			49045	Work Pag	k No: 9M-BOE-18039
Aircraft Type:			AW189	DESC:	SB NO. 342-49-047
Aircraft Reg:			9M-BOE	PAGE:	1 Of 1
Description	Part No	Serial Number	Worksheet Re Item No.	ef No. /	Calibration Due Date
		***************************************	. ,		
				/	
		V			
			/		
					****
					<del></del> .
	/				





342-49-047

Objet : Attestation d'app Subject: Service Bulletin E				9-047.	
	Jannon O				
Important / Important notice:  Après application de ce Bulletin Service, ve After incorporating this Service Bulletin, ple  Support Clients - 8 Chemin of Fax (33) (0)5	ase complete this o	certificate and ma ver Units 3P 62089 - 31019	ail or fax it to: Toulouse Ce		
	on concernant le maté	riel / Equipment inform	nation		
Utilisateur Customer	Réf P/N	N/S - S/N	TSN*	CSN*	N° Appareil Aircraft S/N
GAP / APU	342-50-K	1065	215:14	2126	49045
Mise à jour du livret moteur APU Update of the APU Engine Log Book	Yes No				
Mise à jour de la fiche matricule du générateur de gaz Update of the Gas generator Log Book	Yes No				
Suppression de la plaque d'identification du générateur de gaz Removal of gas generator identification plate	Yes No				
Commentaire Comment					
* TSN = Time Since New (Heures depuis r		Cycles Since Nev	w (Cycles dep	ouis neuf)	
Opération effectuée par: Work performed by:	MUHAMA				
Je certifie que le matériel identifié ci-des l certify that the above-mentioned equipme	sus a été modifié nt has been modifi	selon les direct ed according to the	tives du Bull ne directives (	etin Servic given in thjs	e en objet. Service Bulletin.
Date Nom / Print name		ction / Position		Signatur	
3-1-2024 MUHAMAD		LAE		1000	

Issue: 001

Issue Date: 27-apr-2023



Issue: 001

Issue Date: 27-apr-2023

POWER UNITS

342-49-047

Page 1

## SERVICE BULLETIN

Reference:	342-49-047 - SERVI	CE BULLETIN	
Title:	Update of gas genera	ator configuration	
Issue number:	001		
Issue Date:	27-apr-2023		
Responsible Partn	ner Company:	N0126	
Originator:	F	F1989	
Category:	3	3 - Recommended	i
Applicability:		APU equipped wit	h gas ge <mark>n</mark> erator P/N 341-01-11
Related SB:	3	342-49-046	
Related Document	ts: N	None	
Accomplishment:		Once only	Recurring
Planned to be inco	orporated in Technic	al Publications: ⊠ Yes	□ No
		IJTS PROPRIETARY INFO	1 - 1 - 12 - 12 - 1
any person required to compl	y with the terms of the instruction	ns for maintaining the airw	RAN POWER UNITS. They are made available to vorthiness of the APU.
prior agreement from SAFRA whole or in part for any purp POWER UNITS. If such cons	configuration changes or to obta N POWER UNITS. This docume cose other than maintaining the ent is given, this notice and the r	ain EASA or any other govent shall not be used, copie airworthiness of the APU notice set forth on each pa	ufacture, development, or derivation of any repairs, remment regulatory approval to do so, is subject to ed, reproduced, duplicated, modified or disclosed in J without the express written consent of SAFRAN to develop the subject of the subject of this document shall also be reproduced.
been manufactured and/or ar UNITS technical documentation	al limits, life limits and the like, ha oproved by SAFRAN POWER U on and recommendations, SAFF roved by SAFRAN POWER UNI	ave been developed and a INITS and that have been RAN POWER UNITS has n	y, cleaning, inspection methods and limits, repair pproved for use with equipment and parts that have maintained in accordance with SAFRAN POWER to contractual or legal obligation for, nor knowledge ament is not intended to apply to parts and repairs
	2023 Safran Power Units All	rights reserved. Confide	ntial and Proprietary.



**POWER UNITS** 

342-49-047

#### 1. Revision information

Issue	Date	Reason for update	
001	27-apr-2023	Original issue	·/

### 2. Planning information

#### 2.1. Applicability

This Service Bulletin (SB) is applicable to APU power plant fitted on Leonardo Helicopters AW189/AW149 helicopters, equipped with gas generators P/N 341-01-11.

#### 2.2. Reason

The purposes of this modification is to maintain repair capability of the gas generators by regularizing the gas generator configuration.

The purpose of this Service Bulletin is to introduce modification n°342/445.

#### 2.3. Description

The purpose of this Service Bulletin is to describe the procedure to be performed by the end user or MRO center to retrofit gas generator P/N 341-01-11 into gas generator P/N 341-01-12.

#### 2.4. Compliance

#### 2.4.1. Compliance category

Comply with compliance category 3 - Recommended.

#### 2.4.2. Time of compliance

Do as soon as possible without effect on revenue service.

#### 2.5. Approval

The technical content of this document is approved under the authority of DOA No. EASA 21J214.

#### 2.6. Manpower

Manpower: 0.5 h man hour is necessary to do this service bulletin.

#### 2.7. Material

Not applicable

#### 2.8. Tooling

No additional special tooling is required.

#### 2.9. Weight and balance

The weight is not affected.

The centre of gravity is not affected.

Issue: 001

Page 2

Issue Date: 27-apr-2023



POWER UNITS

342-49-047

#### 2.10. Publication affected

Not applicable.

#### 2,11. Previous modifications

Not applicable.

#### 3. Accomplishment Instructions

#### 3.1. Procedure

- 1. Update of APU Engine Log Book:
  - On the Components Part List (last page of the APU Engine Log Book), strike out the P/N 341-01-11 and rewrite 341-01-12.

Only the last two digits of the P/N can be replaced as shown in Figure 1 below.

SAFRAN			GAP e	APU / moděle 3	42 / e-API	JAPU/mode	1342	
Direction Qualité	Désignation :	Turbomoteur/	Référence :		Indice :		Nº série :	1008
Quality Directorate	Designation .	Turboshaft Engine	P/N:	342-50-11	Issue :	,	SN.	
		LISTE	DES CONST	ITUANTS / C	OMPONENT	S PART LIS	T	
DESIGNATION		RE	F. / P/N	IND / ISSUE	Nº / No.	FME / Log card		OBSERVATIONS / REMARKS
TURBOMOTEUR TURBO SHAFT ENGINE		34	2-50-11		1008	Oni Fer		
* * GENERATEUR DE GAZ GAZ GENERATOR		34	1-01-X-12		1008	Om   Fer		
***BOUGES		S	C3811		0115 : 0116	Non No		Quantity 2
*** SONDE DE TEMPERATURE TEMPERATURE PROBE		. 97	5457-1		0138	Non No		
*** SONDE DE TEMPERATURE TEMPERATURE PROBE		0.2	5475-2		0152	Non No		
* * HARNAIS CONTROLE  ELECTRICAL HARNESS			342-30		02	Non / No		
* * HARNAIS ALIM FILD ELECTRICAL HARNESS			342-30-001		05	Non No		
* * HARNAIS SURVITESSE ELECTRICAL HARNESS		247	-30-002		03	Non No		
**BOITE RELAIS  GEAR BOX		Fore	EQ00-01-200-02		0016	Out / Fer		
** ELECTRO-POMPE  FUEL METERING PUMP		. 14	1449057		61	61 Oui Yes		
* * BLOC HYDRAULIQUE HIDRAULIC BLOCK			MA8931-000		0035	Non / No		
* * BOITIER D ALLUMAGE		1.75	HE3521-2		00190	Non No		
** SONDE DE TEMPERATURE TEMPERATURE PROBE		0.7	975458-1		0145	Non No		
* * CABLE DE BOUGIE		CLI	CLB 3230-1		0266 / 0267	Neu No		Quantity: 2
* * MOTEUR DE LANCEMENT ELECTRICAL STARTER MOTOR		037M	037MBH02V02		C90022	Oui - Yes		
BOTTER ELECTRONIQUE ELECTRONIC CONTROL UNIT		,	342-45		(1)	Oui / Yes		

<sup>(1)</sup> Le bottier électronique étant un équipement dissocié du turbornoteur, son n° de série et sa FME devront être joints au livret moteur du GAP par l'utilisateur.

As the électronic unit is delivered separately of the turbo shaft engine, his S N and his log card must be added on the GAP individual acceptance report by the use

PVRI 523422 Ind A

Figure 1: Update of APU Engine Log Book to be implemented

Issue: 001

Issue Date: 27-apr-2023

Page 3

SAFRAN POWER UNITS PROPRIETARY INFORMATION
Use or disdosure of data contained on this page is subject to the restriction defined on the front page.
NOTE EXPORT CONTROLLED



**POWER UNITS** 

342-49-047

- 2. Update of the Gas Generator Log Book:
  - On the front page of the Gas Generator Log Book, strike out the P/N 341-01-11 and rewrite 341-01-12.

Only the last two digits of the P/N can be replaced as shown in Figure 2 below.



Figure 2: Update of Gas Generator Log Book to be implemented

Issue: 001 Page 4
Issue Date: 27-apr-2023

SAFRAN POWER UNITS PROPRIETARY INFORMATION
Use or disclosure of data contained on this page is subject to the restriction defined on the front page.
NOT EXPORT CONTROLLED



#### **POWER UNITS**

342-49-047

3. Removal of gas generator identification plate

Only the Gas Generator identification plate referring to the PN 341-01-11 is impacted by this procedure. The APU identification plate must remain as it is.

Gas Generator identification plate may have already been removed by MRO Center. In this case, this operation is not required to be performed.

- 3.1. Required conditions
  - 3.1.1. The helicopter must be safe for maintenance.
  - 3.1.2. Refer to the helicopter maintenance manual if the APU is installed.
  - 3.1.3. The access doors must be opened.
- 3.2. Remove and discard the four nuts (Figure 3, 4) and the four screws (3) that attach the identification plate (1) to the identification plate holder (2).
- 3.3. Discard the identification plate (1).




Figure 3: Update of Gas Generator Log Book to be implemented

Issue: 001

Issue Date: 27-apr-2023

Page 5

SAFRAN POWER UNITS PROPRIETARY INFORMATION Use or disclosure of data contained on this page is subject to the restriction defined on the front page. NOT EXPORT CONTROLLED



**POWER UNITS** 

342-49-047

- 3.4. Requirement after job completion
  - 3.4.1. Remove all the tools and the other items from the work area. Make sure that the work area is clean.
  - 3.4.2. The access doors must be closed.

#### 3.2. Record

Record the embodiment of this SERVICE BULLETIN 342-49-047 in the EQUIPMENT LOG CARD of the APU

#### 3.2.1. Compliance certificate

For each APU power plant upgraded, send the following service bulletin compliance certificate to the MANUFACTURER.

Issue: 001 Page 6 Issue Date: 27-apr-2023



#### POWER UNITS

342-49-047

				Bulletin Serv		9-047.	
Important / Important notice Après application de ce Bulletin Ser	e:					Irnor nar a	nurrior ou fav à :
After incorporating this Service Bulle	etin, ple	ase con	nplete this Safran Po	certificate and ma wer Units	ail or fax it to:	•	
	3) (0)5	61 70 7	4 45 - e.m	ail: csc.spu@safr	angroup.com	dex 2, Fran	nce
Utilisateur Customer	Information concernant le matériel / Equipment information						N° Appareil
GAP / APU		Ró	if P/N	N/S - S/N	TSN*	CSN*	Aircraft S/N
Mise à jour du livret moteur APU Update of the APU Engine Log Book		Yes	No				
Mise à jour de la fiche matricule du génér gaz Update of the Gas generator Log Book	ateur de	Yes	No				
Suppression de la plaque d'identification générateur de gaz Removal of gas generalor identification plate		Yes	No				
Commentaire Comment							
* TSN = Time Since New (Heures of Opération effectuée par: Work performed by: Je certifie que le matériel identifie I certify that the above-mentioned e		sus a é	été modifi	é selon les direc	tives du Bull	etin Servic	e en objet.
Date Nom / Pri					Signature		
					-		

Issue: 001

Issue Date: 27-apr-2023

Page 7

SAFRAN POWER UNITS PROPRIETARY INFORMATION
Use or disclosure of data contained on this page is subject to the restriction defined on the front page.
NOT EXPORT CONTROLLED



**POWER UNITS** 

342-49-047

#### 4. Material information

#### 4.1. Support equipment

Not applicable.

#### 4.2. Material requirements

Not applicable.

#### 4.3. List of components

Not applicable.

#### 4.4. Interchangeability

177	
Physical interchangeability:	Not affected
Functional interchangeability:	Not affected
Restriction of mixability:	No restriction

## 4.5. Parts disposition

Not applicable.

#### 4.6. Procurement conditions

Not applicable.

**END OF SERVICE BULLETIN** 

Issue: 001

Page 8

Issue Date: 27-apr-2023