

DELIVERY NOTE WP



DELIVER TO :

GALAXY AEROSPACE (M) SDN. BHD.
 CAMO DEPARTMENT
 Lot 11, MRO Centre,
 Malaysia International Aerospace Centre,
 Sultan Abdul Aziz Shah Airport,
 47200 Subang, Selangor
 Malaysia.
 Attn : Zaty Nadhira binti Mohamed Zuhari

DN NUMBER : GAM/DN/SAAS-24-083

OUR REFERENCE : 9M-SAAS-17212

WO REFERENCE : 2024-17212

DATE COMPLETION: 14 MAY 2024

AJL NUMBER : 002242

A/C TYPE	AW139	A/C REG	9M-SAAS	A/C S/N	31903
OWNER / OPERATOR	GADING AIR SERVICES SDN BHD	A/C TOTAL TIME	524:50	LANDINGS	1239
ENGINE #1 S/N	PCE-KB2390	T.S.N	524:50	T.S.O	-
ENGINE #2 S/N	PCE-KB2380	T.S.N	524:50	T.S.O	-

SB 139-672 PART II	-001	1	1	4	-	-	7

*THIS IS TO CERTIFY THAT TASKS LISTED ABOVE HAS BEEN ACCOMPLISHED AS PER PO/WORK ORDER/SERVICE ORDER NO. AS ABOVE.

NAME	HASMA HIDAYATUL HUSNA	SIGNATURE		DATE	22 MAY 2024 10 JUNE 2024
VERIFIED AND ACCEPTED BY					
DATE		23 - 05 - 2024			

- *WS – WORKSHEET
- *PR – PART REPORT
- *ARC – AUTHORISED RELEASE CERTIFICATE
- *S – SERVICEABLE LABEL
- *SBC – SERVICE BULLETIN COMPLIANCE
- *OTH – OTHERS

WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

Address: Lot 11-14, MRO Centre, Malaysia
 International Aerospace Centre, SAAS Airport,
 Subang
 Malaysia

Attention: Mr. Syafrul Yamani
 Engineering Manager
 syafrul@galaxyaerospace.my

Work Order Number: 2023-17212

Work Pack Reference: 9M-SAAS-17212

Date Issued: 29/09/2023

A/C Registration / SN: 9M-SAAS/31903

Sheet: 1 of 1

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION (MMIR)	SB NO. 139-672, NEW ISSUE (PART II)	<u>6.0</u> (PLEASE ADVISE)

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.


Thank you.
 Best Regards,

Zaty Nadhira Mohamed Zuhari
 Continuing Airworthiness Management Manager
 Email: zaty@galaxyaerospace.my



CLIENT/OWNER: GADING AIR SDN. BHD.	SERIAL NO.	HOURS	LDG/CYCLE		WORKPACK NO:	9M-SAAS-17212
AIRCRAFT TYPE: AW139	AIRCRAFT 31903	524:50	139		WORK/INSP/DESC:	SB 139-672 PART 2
REGISTRATION: 9M-SAAS	#1 ENGINE: PCE-KB2390	524:50	-	-	AERONET JOB NO.:	2023-17212
BASE/FACILITY: WMSA	#2 ENGINE: PCE-KB2380	524:50	-	-	AJL REF NO.:	002242
DATE IN: 13/05/2024 OUT: 14/05/2024			NG / N1	NF / N2	SHEET:	1 OF 1


Reason for raising: PERFORM INSTALLATION OF AUXILIARY LINE RETROMOD I.A.W SB 139-672	Raised by and date: CAMO: Zulkarnaen Ibrahim 29/09/2023	Other requirements/information: NIL
---	---	--

List of scheduled inspection and all work carried out under this workpack including individual reference			DATE INSPECTION COMPLETED	Master Signature Schedule		
NO.	INSPECTION / WORK	WORKSHEET REF		NAME	SIGNATURE	APP/STAMP
1	NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION (MMIR)	17212-001	14/05/2024	LEE BOON HONG	<i>[Signature]</i>	
				HARIZ	<i>[Signature]</i>	8026

Galaxy Aerospace (M) Sdn. Bhd.

I hereby certify the following task has been performed and found satisfactory:


1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan. 4) FOD check has been done.

Sign & Stamp: *[Signature]*  Date & Time: 14.05.24
1700

GAM AMO/2016/02

PART 145 - AMO RELEASE STATEMENT
THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND

OEM PUBLICATION/REVISION AS PER REASON FOR RAISING ABOVE
 IF DIFFERENT FROM ABOVE, OEM PUBLICATION/REVISION.....
 EMM PTGC - GTC REVISION 33.0 DATED 2024-05-06.02
 LAFER APPROVED REVISIONS.....
 * TICK WHERE APPLICABLE

NAME	LEE BOON HONG	
SIGN & APPROVAL	<i>[Signature]</i> 	
FIRM	GAM AMO/2016/02	
DATE	14/05/2024	

PART M - CAMO ACCEPTANCE STATEMENT
THIS IS TO CERTIFY THAT THE ABOVE MENTIONED WORK PACKAGE HAS BEEN REVIEWED, CHECKED FOR COMPLETION AND UPDATED IN THE MAINTENANCE SOFTWARE.

NAME	SIGN & APPROVAL	DATE
NUR HUSNINA BINTI MUHAMAD ZURAIDI	<i>[Signature]</i> 	21/05/24



Tools Report



Aircraft Serial No:	31903	Work Pack No:	9M-SAAS-17212
Aircraft Type:	AW139	DESC:	PERFORM
Aircraft Reg:	9M-SAAS	PAGE:	1 Of 1

Description	Part No	Serial Number	Worksheet Ref No. / Item No.	Calibration Due Date
[Table content is crossed out with a diagonal line]				



CLIENT/OWNER: GADING AIR SDN. BHD.	SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET NO: 17212-001
AIRCRAFT TYPE: AW139	AIRCRAFT: 31903	REFER WORKPACK		WORK/INSP/DESC: NUMBER 4 PUMP LINE
REGISTRATION: 9M-SAAS	#1 ENGINE: PCE-KB2390	REFER WORKPACK		WORKPACK REF: 9M-SAAS-17212
BASE/FACILITY: WMSA	#2 ENGINE: PCE-KB2380	REFER WORKPACK		AJL REF NO.: REFER WORKPACK
DATE IN: REFER WORKPACK OUT: REFER WORKPACK			NG / N1 NF / N2	SHEET: 1 OF 1
Reason for raising: PERFORM INSTALLATION OF AUXILIARY LINE RETROMOD I.A.W SB 139-672 NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION (MMIR)			Raised by and date: CAMO; Zulkarnaen Ibrahim 29/09/2023	Other requirements/information: NIL

Item	Description	Technician	* Eng. CRS	Date
1	<p>SB 139-672 REV. / PART 2 COMPLIANCE</p> <p>TO PERFORM SB 139-672 REV. / PART 2 COMPLIANCE I.A.W. ACCOMPLISHMENT INSTRUCTION OF THE SB 139-672 REV. / PART 2.</p> <p>PART 2 OF THIS SERVICE BULLETIN TO INSTALL RETROMOD P/N 3G2900P00711 WHICH REPLACES EXISTING CLAMP P/N A295A3002A AND BRACKET P/N 3G2920A12251 WITH NEW AND IMPROVED VERSIONS THAT PREVENT CHAFING.</p> <p>REFERENCE: SB 139-672 REV. / DATED 03 OCTOBER 2022</p> <p>COMPLIANCE: WITHIN AND NOT LATER THAN 1200 FLIGHT HOURS OR 12 MONTHS, WHICHEVER OCCURS FIRST AFTER THE ISSUE OF THIS SERVICE BULLETIN, IF DURING COMPLIANCE WITH PART 1 NO CHAFING IS DETECTED OR ITS ENTITY IS NEGLIGIBLE.</p> <p>NOTES: IF CHAFING IS DETECTED AFTER COMPLIANCE PART 1, IMMEDIATELY CARRY OUT PART 2 OF THIS SB.</p> <p>REMARKS: CARRIED OUT, FOUND SATISFACTORY</p>	<p><i>Hain</i></p> <p>2026</p>	<p><i>A</i></p> 	<p>14/05/24</p>

*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. **GAM AMO/2016/02**

*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with _____ and in respect to that work the aircraft / aircraft component is considered ready for release to service.

TICK ✓ WHERE APPLICABLE



PARTS ASSEMBLY RETURNED	DC PASSED	DURICONT M/F	GRAND FIN	FLIGHT	TURBO CH	ADDITIONAL WORKSHEET	STANDARD DEFECT	FLYING PARTS	DATE	TIME	LOG	AIRCRAFT	ENGINE	FUEL	TEMP	REMARKS	MODIFIED BY
-------------------------	-----------	--------------	-----------	--------	----------	----------------------	-----------------	--------------	------	------	-----	----------	--------	------	------	---------	-------------

Please send to the following address: LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988	SERVICE BULLETIN COMPLIANCE FORM	Date: 14/05/2024
Number: 139-672		
Revision: /		

Customer Name and Address:	Telephone:
	Fax:
	B.T. Compliance Date: 14/05/2024

Helicopter Model	S/N	Total Number	Total Hours	T.S.O.
AW139	31903	-	524:50	-

Remarks: CARRIED OUT FOUND SATISFACTORY

Information:

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.



CLIENT/OWNER: GADING AIR SDN. BHD.	SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET NO:	17212-001
AIRCRAFT TYPE: AW139	AIRCRAFT	31903	REFER WORKPACK	WORK/INSP/DESC:	NUMBER 4 PUMP LINE
REGISTRATION: 9M-SAAS	#1 ENGINE:	PCE-KB2390	REFER WORKPACK	WORKPACK REF:	9M-SAAS-17212
BASE/FACILITY: WMSA	#2 ENGINE:	PCE-KB2380	REFER WORKPACK	AJL REF NO.:	REFER WORKPACK
DATE IN: REFER WORKPACK OUT: REFER WORKPACK				SHEET:	1 OF 1

REASON FOR RAISING: PERFORM INSTALLATION OF AUXILIARY LINE RETROMOD I.A.W SB 139-672 NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION (MMIR)	Raised by and date: CAMO; Zulkarnaen Ibrahim 29/09/2023	Other requirements/information: NIL
--	--	--

Item	Part No	Description	Serial Number		Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX	Release Reference
			Off	On					
1.	8G3920A12253	BRACKET	-	-	1	PCMX2	GB	-	GIN 5055
2.	8G3920A01251	SPECIAL BLOCK	-	-	1	PCMX2	GB	-	GIN 5019
3.	MS35489-10X	GROMMET RUBBER	-	-	3	PCMX2	GB	-	GIN 5055
4.	NAS43003-2X	SPACER	-	-	3	PCMX2	GB	-	GIN 4972
5.	MS15795-8A	WASHER	-	-	3	PCMX2	GB	-	GIN 5019
6.	AH305A	BOLT	-	-	3	PCMX2	GB	-	GIN 5084
7.	8G3920L00151	SPECIAL CUSHION	-	-	2	PCMX2	GB	-	GIN 4887
Empty rows with diagonal line									

NAME	FIRM	SIGN & APPROVAL	DATE
LEE BOON HONG	GAM AMO/2016/02	GALAXY AEROSPACE M112 MALAYSIA	14/05/2024

*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with GAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. **GAM AMO/2016/02**

*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with _____ and in respect to that work the aircraft / aircraft component is considered ready for release to service.

TICK WHERE APPLICABLE

WORK SHEET NO	DATE	ISSUED BY	CHKD BY	APPROVED BY	REVISION	STATUS	REMARKS	DATE	BY	REVISION	STATUS	REMARKS	DATE	BY	REVISION	STATUS	REMARKS	DATE	BY
---------------	------	-----------	---------	-------------	----------	--------	---------	------	----	----------	--------	---------	------	----	----------	--------	---------	------	----

SERVICEABLE



GalaxyAerospace
maintenance . repair . overhaul

ITEM ID:	57006		
DESCRIPTION:	BRACKET		
PART NO:	3G2920A12253	QTY:	1.00
SERIAL NO:		BIN:	B-10-4 --
CONDITION:	NE	LOCATION:	WAREHOUSE BONDED
TSN:	N/A	TSO:	N/A
SHELF DUE / EXP DATE:	N/A		
JOB ID:	17212	PO ID:	
		SIGN:	
GIN / ID. NO:	GIN5055	APPROVAL:	16/11/2023

GAM/E-005 Rev 2 (01/21)

SERVICEABLE



GalaxyAerospace
maintenance . repair . overhaul

ITEM ID:	56713		
DESCRIPTION:	SPECIAL BLOCK		
PART NO:	8G2920A01251	QTY:	1.00
SERIAL NO:		BIN:	B-31 --
CONDITION:	NE	LOCATION:	WAREHOUSE BONDED
TSN:	N/A	TSO:	N/A
SHELF DUE / EXP DATE:	N/A		
JOB ID:	17212	PO ID:	
		SIGN:	
GIN / ID. NO:	GIN5019	APPROVAL:	08/11/2023

GAM/E-005 Rev 2 (01/21)

1. Approving Competent Authority/Country ENAC / ITALY		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number AGU - 2022 - IT13 - 10603	
4. Organisation name and address: Leonardo S.p.a. - Helicopters Piazza Monte Grappa 4 00195 ROMA, Italy		5. Work Order/Contract/Invoice Ref. Ord. N. 4802489310 Ref. P.L. N. 0008317731		11. Status/Work NEW	
6. Item	7. Description	8. Part No	9. Qty.	10. Serial No	11. Status/Work
000001	BRACKET	3G2920A12253 --- LAST ITEM ---	140 N	N.A.	NEW
12. Remarks batch n° 18316					
13a. Certifies that the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> approved design data and are in a condition for safe operation <input type="checkbox"/> non-approved design data specified in block 12		13b. Authorised Signature <i>Colombo</i> Colombo Valerio		13c. Approval/Authorisation Number IT.21G.0007	
13d. Name Colombo Valerio		13e. Date (dd mmm yyyy) 18 Feb 2022		14a. <input type="checkbox"/> Part 145.A.50 Release to Service Other Regulation Specified in block 12 <small>Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12 was accomplished in accordance with Part 145 and in respect to that work the items are considered released for Release to Service</small>	
14b. Authorised Signature		14c. Certificate/Approval Ref.N.		14d. Name	
14e. Date (dd mmm yyyy)		14f. Date (dd mmm yyyy)		14g. Date (dd mmm yyyy)	

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s)
 Where the user / installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user / installer ensures that his / her airworthiness authority accepts items from the airworthiness authority specified in block 1.
 Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.





1. Approving Competent Authority/Country ENAC / ITALY		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1			3. Form Tracking Number AGU - 2022 - IT13 - 11030	
4. Organisation name and address: Leonardo S.p.a. - Helicopters Piazza Monte Grappa 4 00195 ROMA, Italy		5. Work Order/Contract/Invoice Ref. Ord. N. 4802489310 Ref. P.L. N. 0008334027		11. Status/Work NEW		
6. Item	7. Description	8. Part No	9. Qty.	10. Serial No	11. Status/Work	
000001	SPECIAL BLOCK	8G2920A01251 -- LAST ITEM --	200 N	N.A.	NEW	
12. Remarks 000001 WO 18317-447P						
13a. Certifies that the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> approved design data and are in a condition for safe operation <input type="checkbox"/> non-approved design data specified in block 12						
13b. Authorised Signature <i>Zomegnan Marco</i>		13c. Approval/Authorisation Number IT.21G.0007		14a. <input type="checkbox"/> Part 145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work the items are considered satisfactory for Release to Service		
13d. Name Zomegnan Marco		13e. Date (dd mmm yyyy) 25 Mar 2022		14b. Authorised Signature		
				14c. Certificate/Approval Ref.N.		
				14d. Name		
				14e. Date (dd mmm yyyy)		
USER/INSTALLER RESPONSIBILITIES						
<ul style="list-style-type: none"> This certificate does not automatically constitute authority to install the item(s) Where the user / installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user / installer ensures that his / her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown. 						



SERVICEABLE



GalaxyAerospace
maintenance . repair . overhaul



ITEM ID:	57007	
DESCRIPTION:	GROMMET RUBBER	
PART NO:	MS35489-10X	QTY: 3.00
SERIAL NO:		BIN: B-10-4 --
CONDITION:	NE	LOCATION: WAREHOUSE BONDED
TSN:	N/A	TSO: N/A
SHELF DUE / EXP DATE:	01/06/2041	
JOB ID:	17212	PO ID:
GIN / ID. NO:	GIN5055	APPROVAL:
		
		SIGN: 
		16/11/2023

GAM/E-005 Rev 2 (01/21)

SERVICEABLE



GalaxyAerospace
maintenance . repair . overhaul

ITEM ID:	56309	
DESCRIPTION:	SPACER	
PART NO:	NAS43DD3-20N	QTY: 3.00
SERIAL NO:		BIN: F-08-05 --
CONDITION:	NE	LOCATION: WAREHOUSE BONDED
TSN:	N/A	TSO: N/A
SHELF DUE / EXP DATE:	N/A	
JOB ID:	17212	PO ID:
GIN / ID. NO:	GIN4972	APPROVAL:
		
		SIGN: 
		26/10/2023

GAM/E-005 Rev 2 (01/21)



PKL0071329794

PACKING LIST - BOLLA CONSEGNA N. 0071329794 / 15.09.2023

SPEDITO A / SHIPPED TO

LEONARDO SPA - MY20
Lot 10, JALAN TEKNOLOGI, TAMAN SAINS SELANGOR 1
c/o AW MALAYSIA LOGISTIC CENTRE
47810 PETALING JAYA
MALAYSIA

LEONARDO SPA
c/o AW Malaysia Logistic Centre
Lot 10, Jalan Teknologi
Taman Sains Selangor 1,
47810 Petaling Jaya
Selangor, Malaysia

CAUSALE TRASPORTO / TERMS OF DELIVERY Transf plant abroad		CLIENTE / CUSTOMER	MEZZO DI SPEDIZIONE / METHOD OF SHIPMENT As per Contract	INCOTERMS DDU - Delivered Duty Unpaid	DATA UMI/ DATE GI	PAG. / PAGE 1 / 1 NT
--	--	--------------------	---	--	-------------------	----------------------------

COMM. / ORDER	ITEM	PART NUMBER	U.M.	QUANTITY	PARTITA / BATCH	SERIAL	SCAD. / EXP	N.S.N. / ANNOTATIONS
4803011624/ 000010	1 C1	MS35489-10X GROMMET	N N	12,000 12,000	0005351089		01.06.2041	C.O.C. - K7T8TW
Certificate of Conformance Leonardo Helicopters hereby certifies that standard items are in conformity with all current governmental and manufacturer's requirements, specifications and drawings. All items are in new condition and are traceable to Leonardo Helicopters. Traceability data are available on request.								

CONFEZIONE / PACKING SCATOLA 30x20x10	PESO LORDO / GROSS WEIGHT 0,280 KG	PESO NETTO / NET WEIGHT 0,080 KG	DIMENSIONI / DIMENSIONS 0,300x0,200x0,100 M
--	---------------------------------------	-------------------------------------	--



0071329794



PRIORITA' / PRIORITY O3 Routine



Leonardo S.p.a.
Sede legale: Piazza Monte Gioppa, 4 - 00195 Roma -
Capitale Sociale €2.543.861.738,00 i.v.
Registro Imprese c/o la CCIAA di Roma, Codice Fiscale, n 00401990585
Partita Iva: P.I.: IT 00881841001



PXL0071319734

Stabilimento di
Logistic Centre Prod. Support
Scarico merce via Cascina Nuo 100
21029 VERGATE (VA)

PACKING LIST - BOLLA CONSEGNA N. 0071319734 / 24.08.2023

CLIENTE / CUSTOMER

LEONARDO SPA - MY20
Lot 10, JALAN TEKNOLOGI, TAMAN SAINS SELANGOR 1
c/o AW MALAYSIA LOGISTIC CENTRE
47810 PETALING JAYA
MALAYSIA

LEONARDO SPA
c/o AW Malaysia Logistic Centre
Lot 10, Jalan Teknologi
Taman Sains Selangor 1,
47810 Petaling Jaya
Selangor, Malaysia

SPEDITO A / SHIPPED TO

CAUSALE TRASPORTO / TERMS OF DELIVERY
Transf plant abroad

CLIENTE / CUSTOMER

MEZZO DI SPEDIZIONE / METHOD OF SHIPMENT
As per Contract

INCOTERMS
DDU - Delivered Duty Unpaid

DATA UM/ DATE GI
1/ 1

PAG. / PAGE
NT

COMM. / ORDER

PART NUMBER

U.M.

QUANTITY

PARTITA / BATCH

SERIAL

SCAD. / EXP

N.S.N. / ANNOTATIONS

4802979561/
000010

NAS43DD3-20N
SPACER,SLEEVE

N

30,000

0005671009

31.12.9999

5365-01-298-3144

C.O.C. - 4902494287

Certificate of Conformance
Leonardo Helicopters hereby certifies that standard items are in conformity with all current governmental and manufacturer's requirements, specifications and drawings. All items are in new condition and are traceable to Leonardo Helicopters. Traceability data are available on request.

CONFEZIONE / PACKING

SCATOLA 30x20x10

PESO LORDO / GROSS WEIGHT

0,230 KG

PESO NETTO / NET WEIGHT

0,030 KG

DIMENSIONI / DIMENSIONS




0,300x0,200x0,100 M






0071319734

PRIORITA' / PRIORITY 03 Routine

Leonardo Malaysia
Sch. Bhd.
COPIA CONFORME ALL'ORIGINALE
COPY OF ORIGINAL

SERVICEABLE			GalaxyAerospace maintenance . repair . overhaul
ITEM ID:	56714		
DESCRIPTION:	WASHER		
PART NO:	MS15795-849	QTY:	3.00
SERIAL NO:		BIN:	6-04-03 --
CONDITION:	NE	LOCATION:	WAREHOUSE BONDED
TSN:	N/A	TSO:	N/A
SHELF DUE / EXP DATE:		N/A	
JOB ID:	17212	PO ID:	SIGN:  08/11/2023
GIN / ID. NO:	GiN5019	APPROVAL:	
			

GAM/E-005 Rev 2 (01/21)

SERVICEABLE			GalaxyAerospace maintenance . repair . overhaul
ITEM ID:	57274		
DESCRIPTION:	BOLT		
PART NO:	AN3C5A	QTY:	3.00
SERIAL NO:		BIN:	0-02-07 --
CONDITION:	NE	LOCATION:	WAREHOUSE BONDED
TSN:	N/A	TSO:	N/A
SHELF DUE / EXP DATE:		N/A	
JOB ID:	17212	PO ID:	SIGN:  27/11/2023
GIN / ID. NO:	GiN5084	APPROVAL:	
			

GAM/E-005 Rev 2 (01/21)

CLIENTE / CUSTOMER		CAUSALE TRASPORTO / TERMS OF DELIVERY		CLIENTE / CUSTOMER		MEZZO DI SPEDIZIONE / METHOD OF SHIPMENT		INCOTERMS		DATA UM / DATE GI		PAG. / PAGE	
LEONARDO SPA - MY20 Lot 10, JALAN TEKNOLOGI, TAMAN SAINS SELANGOR 1 c/o AW MALAYSIA LOGISTIC CENTRE 47810 PETALING JAYA MALAYSIA		Transf plant abroad		As per Contract		DDU - Delivered Duty Unpaid		DDU - Delivered Duty Unpaid		04.10.2023		1 / 1 NT 20598864	
COMM. / ORDER	ITEM	PART NUMBER	U.M.	QUANTITY	PARTITA / BATCH	SERIAL	SCAD. / EXP	N.S.N. / ANNOTATIONS					
4803004430/ 000010	1 C1	MS15795-849 WASHER	N N	3,000 3,000	0006840815		31.12.9999	5310-01-297-7555 C.O.C. - 18884785	Certificate of Conformance Each product, parts or appliances quoted in this packing list have been packaged and for correct embodiment of any applicable service bulletin and or airworthiness directive, before their delivery. Each ARC received by our facility is maintained on file pursuant to our record retention procedures. When original ARC is not supplied, the organisation certifies each attached ARC is a true copy.				
CONFEZIONE / PACKING		PESO LORDO / GROSS WEIGHT		PESO NETTO / NET WEIGHT		DIMENSIONI / DIMENSIONS							
SCATOLA 20x20x10		0,180 KG		0,020 KG		0,200x0,200x0,100 M		PRIORITA'/PRIORITY 03 Routine					

Leonardo Malaysia
Sdn. Bhd.
COPIA CONFORME ALL'ORIGINALE
COPY OF ORIGINAL



PKL0071346283

PACKING LIST - BOLLA CONSEGNA N. 0071346283 / 27.10.2023

CLIENTE / CUSTOMER		CAUSALE TRASPORTO / TERMS OF DELIVERY		CLIENTE / CUSTOMER		MEZZO DI SPEDIZIONE / METHOD OF SHIPMENT		INCOTERMS		DATA UM/ DATE GI		PAG. / PAGE	
LEONARDO SPA - MY20 Lot 10, JALAN TEKNOLOGI, TAMAN SAINS SELANGOR 1 c/o AW MALAYSIA LOGISTIC CENTRE 47810 PETALING JAYA MALAYSIA		Transf plant abroad		As per Contract		DDU - Delivered Duty Unpaid		DDU - Delivered Duty Unpaid		1 / 1		NT	
COMM. / ORDER	ITEM	PART NUMBER	U.M.	QUANTITY	PARTITA / BATCH	SERIAL	SCAD. / EXP	N.S.N. / ANNOTATIONS					
4803051728/ 000010	1 C1	AN3C5A BOLT,MACHINE	N N	1.000,000 1.000,000	0005796836		31.12.2999	5306-00-150-9527 C.O.C. - H1BFB1.101		All items are in new condition and are traceable to Leonardo Helicopters. Traceability data are available on request.			
CONFEZIONE / PACKING		PESO LORDO / GROSS WEIGHT		PESO NETTO / NET WEIGHT		DIMENSIONI / DIMENSIONS							
SCATOLA 40x20x20		4,270 KG		3,890 KG		0,400x0,200x0,200 M							



0071346283

Leonardo Malaysia
Sdn. Bhd.
COPIA CONFORME ALL'ORIGINALE
COPY OF ORIGINAL

PRIORITA' / PRIORITY 02 URG

1. Approving Competent Authority/Country ENAC / ITALY		2. Organisation name and address: Leonardo S.p.a. - Helicopters Piazza Monte Grappa 4 00195 ROMA, Italy		3. Form Tracking Number AGU - 2022 - IT13 - 10434	
4. Organisation name and address:		5. Work Order/Contract/Invoice Ref. Ord. N. 4802489310 Ref. P.L. N. 0008319253		11. Status/Work NEW	
6. Item 000001	7. Description SPECIAL CUSHION	8. Part No 8G2920L00151 --- LAST ITEM ---	9. Qty. 2.212 N	10. Serial No N.A.	
12. Remarks LOT N° 01 2021 11191.010					
13a. Certifies that the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> approved design data and are in a condition for safe operation <input type="checkbox"/> non-approved design data specified in block 12					
13b. Authorised Signature <i>Marco Righetto</i>		13c. Approval/Authorisation Number IT.21G.0007		14a. <input type="checkbox"/> Part 145.A.50 Release to Service <input type="checkbox"/> Other Regulation Specified in Block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work the items are considered satisfactory for Release to Service	
13d. Name MARCO RIGHETTO		13e. Date (dd mmm yyyy) 10 Feb 2022		14b. Authorised Signature	
				14c. Certificate/Approval Ref.N.	
				14d. Name	
				14e. Date (dd mmm yyyy)	
<p>USER/INSTALLER RESPONSIBILITIES</p> <p>This certificate does not automatically constitute authority to install the item(s) Where the user / installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user / installer ensures that his / her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>					

Leonardo Malaysia
Sdn. Bhd.

COPIA CONFORME ALL ORIGINALE
COPY OF ORIGINAL