






| LIMITED LIFE COMPONENTS INSTALLED ON ASSY | | | | | | | | | | | |
|---|--------------------------|-----------------------|----------------------|---|--------------------------|-----------------------|----------------------|------------------------------|----------|--------------|--------------------|
| REMOVAL | | | INSTALLATION | | | | COMPONENT DATA | | | | |
| STAMP AND SIGNATURE (39) | COMP. TIME SINCE OH (38) | COMP. TOTAL TIME (37) | ASSY TOTAL TIME (36) | STAMP AND SIGNATURE (35) | COMP. TIME SINCE OH (34) | COMP. TOTAL TIME (33) | ASSY TOTAL TIME (32) | RETIREMENT LIFE (31) | S/N (30) | P/N (29) | DESCRIPTION (28) |
| | | | |  | | | | 95,800 | | | UPPER FITTING ASSY |
| | | | |  | | | | 95,800 | | | UPPER FITTING ASSY |
| | | | |  | | | | 15,300 HRS / 54,000 LANDINGS | V403 | 3G6320A01854 | SHAFT MAIN ROTOR |
| | | | |  | | | | ON-CONDITION | 1500 | 3G6320V04252 | PUMP |
| | | | |  | | | | ON-CONDITION | 1474 | 3G6320V04252 | PUMP |


Part n°

Chapter n° 63

Sezione 2A

LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.



AgustaWestland
A Finmeccanica Company

| LIMITED LIFE COMPONENTS INSTALLED ON ASSY | | | | | | | | | | | |
|---|--------------------------|-----------------------|----------------------|--------------------------|--------------------------|-----------------------|----------------------|----------------------|----------|----------|------------------|
| REMOVAL | | | INSTALLATION | | | | COMPONENT DATA | | | | |
| STAMP AND SIGNATURE (39) | COMP. TIME SINCE OH (38) | COMP. TOTAL TIME (37) | ASSY TOTAL TIME (36) | STAMP AND SIGNATURE (35) | COMP. TIME SINCE OH (34) | COMP. TOTAL TIME (33) | ASSY TOTAL TIME (32) | RETIREMENT LIFE (31) | S/N (30) | P/N (29) | DESCRIPTION (28) |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

Part n°

Chapter n° 63

Sezione 2D

LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.



AgustaWestland
A Finmeccanica Company

LOG CARD

Sezione 2

63

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Chapter n°

Part n°

| LIMITED LIFE COMPONENTS INSTALLED ON ASSY | | | | | | | | | | | |
|---|--------------|----------------------|------------------------------|----------------------|-----------------------|--------------------------|--------------------------|----------------------|-----------------------|--------------------------|--------------------------|
| COMPONENT DATA | | | | INSTALLATION | | | | REMOVAL | | | |
| DESCRIPTION (28) | P/N (29) | S/N (30) | RETIREMENT LIFE (31) | ASSY TOTAL TIME (32) | COMP. TOTAL TIME (33) | COMP. TIME SINCE OH (34) | STAMP AND SIGNATURE (35) | ASSY TOTAL TIME (36) | COMP. TOTAL TIME (37) | COMP. TIME SINCE OH (38) | STAMP AND SIGNATURE (39) |
| MR FWD SERVO BRACKET ASSY | 3G6230A02231 | V394 | ON CONDITION | 00:00 | 00:00 | NEW | | | | | |
| MR AFT SERVO BRACKET ASSY | 3G6230A02331 | V710 | ON CONDITION | 00:00 | 00:00 | NEW | | | | | |
| MR AFT SERVO BRACKET ASSY | 3G6230A02331 | V706 | ON CONDITION | 00:00 | 00:00 | NEW | | | | | |
| MGB MAIN CASE ASSY | 3G6320A02738 | V277 ^{P500} | 19,000 HRS / 77,500 LANDINGS | 00:00 | 00:00 | NEW | | | | | |
| MGB TOP CASE ASSY | 3G6320A01035 | V357 | 17,000 HRS | 00:00 | 00:00 | NEW | | | | | |
| ANTITORQUE BEAM | 3G6330A00532 | LMA0260 | 20,000 HRS / 63,000 LANDINGS | 00:00 | 00:00 | NEW | | | | | |
| INPUT MODULE ASSY | 3K6320A00136 | KHI-E06 | ON CONDITION | 00:00 | 00:00 | NEW | | | | | |
| INPUT MODULE ASSY | 3K6320A00136 | KHI-E10 | ON CONDITION | 00:00 | 00:00 | NEW | | | | | |
| CROSS SHAFT ASSY | 3K6320A05831 | KHI-WST-AA77 | ON CONDITION | 00:00 | 00:00 | NEW | | | | | |
| CROSS SHAFT ASSY | 3K6320A05831 | KHI-WST-AA82 | ON CONDITION | 00:00 | 00:00 | NEW | | | | | |
| UPPER FITTING ASSY | 3G6330A00234 | V1834 | 95,800 LANDINGS | 00:00 | 00:00 | NEW | | | | | |
| UPPER FITTING ASSY | 3G6330A00234 | V1835 | 95,800 LANDINGS | 00:00 | 00:00 | NEW | | | | | |

Rev. 3

AQ 12-04

LOG CARD

Sezione 3

63

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Chapter n°

Part n°

| ACTIVITY RECORD | | | | | | |
|-----------------|----------------------|-----------|---------------|-----------|-------------------|--------------------------|
| DATE (40) | ASSY TOTAL TIME (41) | TASK (42) | ACTIVITY (43) | DATE (44) | ORGANIZATION (45) | STAMP AND SIGNATURE (46) |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

Rev. 3

AQ 12-04

| ASSEMBLY HISTORICAL RECORD | | | | | | | | | | | | | | | | |
|----------------------------|---------------|----------|-----|-----------------|-----------------|--------------------|-------------------|--------------------------|-----------|-----|-----------------|-----------------|--------------------|------------------------|-------------------|--------------------------|
| INSTALLATION | | | | | | REMOVAL | | | | | | | | | | |
| DATE (13) | R. MARKS (14) | N/C (15) | A/C | TOTAL TIME (16) | TOTAL TIME (17) | TIME SINCE OH (18) | ORGANIZATION (19) | STAMP AND SIGNATURE (20) | DATE (21) | A/C | TOTAL TIME (22) | TOTAL TIME (23) | TIME SINCE OH (24) | REASON OF REMOVAL (25) | ORGANIZATION (26) | STAMP AND SIGNATURE (27) |
| 10-28-13 | N157MM | 41356 | | 00:00 | 00:00 | | AWPC | | | | | | | | | |



NOTES (12)

| | | | | | |
|--------------|--------------|--------------|------------|--------------|--------------|
| 100000065244 | 400000031301 | 100000069354 | 6000004593 | 100000059744 | 400000024970 |
|--------------|--------------|--------------|------------|--------------|--------------|

| DESCRIPTION (1) | P/N (2) | S/N (3) | MANUFACTURER NAME (4) | ASSEMBLY DATE (5) | RETIREMENT LIFE (6) | P/N (7) | S/N (8) | MANUFACTURER NAME (9) | DATE OF CHANGE (10) | RETIREMENT LIFE (11) |
|-------------------|--------------|---------|-----------------------|-------------------|---------------------|---------|---------|-----------------------|---------------------|----------------------|
| GEARBOX ASSY MAIN | 3G6320A00135 | V100 | AGUSTA WESTLAND | 9/2013 | ON-CONDITION | | | | | |



A Finmeccanica Company

LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Part n°
Chapter n°
Sezione 1
63

| DIRECTIVES COMPLIANCE | | | | | | | | | | |
|-----------------------|------------|-------------------------|-------------------|----------------------|-----------------------|------------|-------------------------|-------------------|----------------------|--|
| MANDATORY DIRECTIVES | | | | | OPTIONAL DIRECTIVES | | | | | |
| DIRECTIVE NUMBER (47) | ISSUE (48) | DATE OF COMPLIANCE (49) | ORGANIZATION (50) | STAMP SIGNATURE (51) | DIRECTIVE NUMBER (47) | ISSUE (48) | DATE OF COMPLIANCE (49) | ORGANIZATION (50) | STAMP SIGNATURE (51) | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |



A Finmeccanica Company

LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Part n°
Chapter n°
Sezione 4
63