



# LOG CARD

Sezione 2/A

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Chapter n° .....  
Part n° .....

## LIMITED LIFE COMPONENTS INSTALLED ON ASSY

COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	P/N (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)
Main Rotor Hub assy	109-0111-03-113	P340		00:00	00:00	NEW					
<i>elastomeric bearing</i> Cuscinetto Elastomerico	109-0111-04-101	LK1682		"	"	"					
Cuscinetto Elastomerico	109-0111-04-101	LK1777		"	"	"					
Cuscinetto Elastomerico	109-0111-04-101	LK1778		"	"	"					
Cuscinetto Elastomerico	109-0111-04-101	LK1662		"	"	"		3109 40	3109 40	NEW	
Damper Bracket assy	109-0111-07-113	N1217	✓	"	"	"		3109 40	3109 40	NEW	<i>REP DR</i>
Damper Bracket assy	109-0111-07-113	N1218	✓	"	"	"		3109 40	3109 40	NEW	<i>REP DR</i>
Damper Bracket assy	109-0111-07-113	N1219	✓	"	"	"		3109 40	3109 40	NEW	<i>REP DR</i>
Damper Bracket assy	109-0111-07-113	N1220	✓	"	"	"		3109 40	3109 40	NEW	<i>REP DR</i>
Sliding Ring assy	109-0111-09-101	P450		"	"	"					
Flange Ass. Sciss. Bracket	109-0111-11-105	N344		"	"	"					
Drop Stop Plate	109-0111-17-101	P1867		"	"	"					