

AGUSTA

UNA SOCIETA' DI AGUSTAWESTLAND



LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED

Sezione 1

Chapter n°

Part n°

7DESCRIPTION (1) Main Landing Gear Shock Absorber	P/N (2) 3G3210V01031	S/N (3) 25030	MANUFACTURER NAME (4) Hydromash	ASSEMBLY DATE (5) 04.2016	RETIREMENT LIFE (6)
	P/N (7) 1654C0000-01	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)

NOTES (12)

ASSEMBLY HISTORICAL RECORD

INSTALLATION							REMOVAL							
DATE (13)	A/C		ASSY			ORGANIZATION (19)	STAMP AND SIGNATURE (20)	DATE (21)	A/C TOTAL TIME (22)	ASSY		REASON OF REMOVAL (25)	ORGANIZATION (26)	STAMP AND SIGNATURE (27)
	R. MARKS (14)	N/C (15)	TOTAL TIME (16)	TOTAL TIME (17)	TIME SINCE OH (18)					TOTAL TIME (23)	TIME SINCE OH (24)			
18-6-2019	9m-YTL	41358	192:58	NEW	NEW	AWM								