


DESCRIPTION (1) <b>SLIDING CONTROL ASSY</b>	P/N (2) <b>3G6430A02531</b>	S/N (3) <b>724</b>	MANUFACTURER NAME (4) <b>Leonardo S.p.A.</b>	ASSEMBLY DATE (5) <b>DECEMBER 16</b>	RETIREMENT LIFE / TIME LIMITS (6) <b>ON CONDITION</b>
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11)

NOTE

### ASSEMBLY HISTORICAL RECORD

INSTALLATION						REMOVAL							
DATE (12)	A/C		ASSY			ORGANIZATION, STAMP AND SIGNATURE (18)	DATE (19)	A/C		ASSY		REASON OF REMOVAL (24)	ORGANIZATION, STAMP AND SIGNATURE (25)
	R. MARKS (13)	TOTAL FLIGHT HOURS (15)	TOTAL HOURS (16)	TIME SINCE OH (17)	TOTAL FLIGHT HOURS (20)			ACTUAL TOTAL HOURS (21)	TOTAL HOURS WITH PENALTY FACTOR (22)	TIME SINCE OH (23)			
		TOTAL LANDINGS (15)	TOTAL LANDINGS (16)	LANDS SINCE OH (17)	TOTAL LANDINGS (20)			ACTUAL TOTAL LANDINGS (21)	TOTAL LANDS WITH PENALTY FACTOR (22)	LANDINGS SINCE OH (23)			
S/N (14)	TOTAL LIFTS/CYCLES (15)	TOTAL LIFTS/CYCLES (16)	LIFTS/CYCLES SINCE OH (17)	TOTAL LIFTS/CYCLES (20)	ACTUAL TOTAL LIFTS/CYCLES (21)	TOTAL LANDS WITH PENALTY FACTOR (22)	LIFTS/CYCLES SINCE OH (23)						
FEB. 17		00.00	00.00	NEW	Leonardo Helicopters								
	31763												



# LOG CARD

## Section 2

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

ATA Chapter \_\_\_\_\_

64

### COMPONENTS INSTALLED ON ASSY

ASSY P/N (26)

3G6430A02531

ASSY S/N (27)

724

COMPONENT DATA			INSTALLATION				REMOVAL				
DESCRIPTION (28)	P/N (29)	MANUFACTURING DATE (31)	ASSY TOTAL HOURS (33)	COMPONENT TOTAL HOURS (34)	COMPONENT TIME SINCE OH (35)	DATE (36)	ASSY TOTAL HOURS (38)	COMPONENT TOTAL HOURS (39)	COMPONENT		DATE (42)
	S/N (30)	RETIREMENT LIFE / TIME LIMITS (32)	TOTAL LANDINGS (33)	TOTAL LANDINGS (34)	LANDINGS SINCE OH (35)	STAMP AND SIGNATURE (37)	TOTAL LANDINGS (38)	TOTAL LANDINGS (39)	TOTAL HOURS WITH PENALTY FACTOR (40)	TIME SINCE OH (41)	STAMP AND SIGNATURE (43)
			TOTAL LIFTS/CYCLES (33)	TOTAL LIFTS/CYCLES (34)	LIFTS/CYCLES SINCE OH (35)		TOTAL LIFTS/CYCLES (38)	TOTAL LIFTS/CYCLES (39)	TOTAL LANDINGS WITH PENALTY FACTOR (40)	LIFTS/CYCLES SINCE OH (41)	
TAIL ROTOR DUPLEX BEARING	3G6430V00153	12/2016	00.00	00.00	NEW	02/2017	134:38	134:38			07-02-19
	16207	3000 FH					348				KINGWING
TAIL ROTOR DUPLEX BEARING	3G6430V00153		134:38	00:00	NEW	07-02-19					
	18340	3000 FH	348			KINGWING					
			65								



# LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

## Section 3

ATA Chapter

64

### ASSEMBLY ACTIVITY HISTORY


ASSY P/N (44)

3G6430A02531

ASSY S/N (45)

724

DATE (46)	TOTAL HOURS (47)	TASKS (48)	ACTIVITIES (49)	ORGANIZATION (50)	STAMP AND SIGNATURE (51)
	TOTAL LANDINGS (47)				
	TOTAL LIFTS/CYCLES (47)				



# LOG CARD

## Section 4

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

ATA Chapter

64

### AIRWORTHINESS DIRECTIVES AND BULLETINS COMPLIANCE

ASSY P/N (52) **3G6430A02531**

ASSY S/N (53) **724**

#### AIRWORTHINESS DIRECTIVE AND MANDATORY BULLETINS

#### OPTIONAL BULLETINS

AIRWORTHINESS DIRECTIVE/MANDATORY BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)	ORGANIZATION (58)	STAMP AND SIGNATURE (59)	OPTIONAL BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)	ORGANIZATION (58)	STAMP AND SIGNATURE (59)
ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)			ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)		
		ASSY TOTAL LIFTS/CYCLES (57)					ASSY TOTAL LIFTS/CYCLES (57)		