



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Section 2

ATA Chapter _____ 63

COMPONENTS INSTALLED ON ASSY

ASSY P/N (26)		3G6320A00134				ASSY S/N (27)		AW858			
COMPONENT DATA			INSTALLATION				REMOVAL				
DESCRIPTION (28)	P/N (29)	MANUFACTURING DATE (31)	ASSY TOTAL HOURS (33)	COMPONENT TOTAL HOURS (34)	COMPONENT TIME SINCE OH (35)	DATE (36)	ASSY TOTAL HOURS (38)	COMPONENT TOTAL HOURS (39)	TOTAL HOURS WITH PENALTY FACTOR (40)	TIME SINCE OH (41)	DATE (42)
	S/N (30)	RETIREMENT LIFE / TIME LIMITS (32)	TOTAL LANDINGS (33)	TOTAL LANDINGS (34)	LANDINGS SINCE OH (35)	STAMP AND SIGNATURE (37)	TOTAL LANDINGS (38)	TOTAL LANDINGS (39)	TOTAL LANDINGS WITH PENALTY FACTOR (40)	LANDINGS SINCE OH (41)	STAMP AND SIGNATURE (43)
			TOTAL LIFTS/CYCLES (33)	TOTAL LIFTS/CYCLES (34)	LIFTS/CYCLES SINCE OH (35)		TOTAL LIFTS/CYCLES (38)	TOTAL LIFTS/CYCLES (39)		LIFTS/CYCLES SINCE OH (41)	
PUMP, LUBRICATION	3G6320V04252	12/2017	00.00	00.00	NEW	03/2018					
	2207	5000 OH									
UPPER FITTING ASSY	3G6330A00234	12/2017	00.00	00.00	NEW	03/2018					
	3427	133240 Land.									
UPPER FITTING ASSY	3G6330A00234	12/2017	00.00	00.00	NEW	03/2018					
	3517	133240 Land.									
UPPER FITTING ASSY	3G6330A00234	12/2017	00.00	00.00	NEW	03/2018					
	3518	133240 Land.									
UPPER FITTING ASSY	3G6330A00234	12/2017	00.00	00.00	NEW	03/2018					
	3520	133240 Land.									
ANTITORQUE BEAM ASSY	3G6330A00532	12/2017	00.00	00.00	NEW	03/2018					
	MOR0081	20000 FH 63000 Land.									
MODULE INPUT SHAFT	3K6320A00136	12/2017	00.00	00.00	NEW	03/2018					
	KHI-L48	On Condition									