

R44 SB 110 COMPLIANCE

AD/SB ID: 3761 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: C029-3 TAIL ROTOR BLADE CRACKS

Title/Subject: R44 SB 110 PART A

Version No:

Reason For Raising:

URL:

Date: 06 / 01 / 2022

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

	Title	Filename
R44 SB 110		3761-1478.pdf

AD/SB ID: 3761 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
	9M-AMA	Airframe Hours	-	Hours	10	-	-	NOT APPLICABLE

AD/SB ID: 3763 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: C029-3 TAIL ROTOR BLADE CRACKS

Title/Subject: R44 SB 110 PART B

Version No:

Reason For Raising:

URL:

Date: 06 / 01 / 2022

Tolerance: 0 % (Whole numbers only)

Creep Type: Creep on Completion Unit

Document:

	Title	Filename
	R44 SB 110	3763-1479.pdf

AD/SB ID: 3763 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-AMA	Date (Months)	-	Months	3	-	-	NOT APPLICABLE	