

WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

<p>Address: Lot 11-14, MRO Centre, Malaysia International Aerospace Centre, SAAS Airport, Subang Malaysia</p> <p>Attention: Mr. Syafrul Yamani Engineering Manager syafrul@galaxyaerospace.my</p>	<p>Work Order Number: 2021-8911</p> <p>Work Pack Reference: 9M-BOB-8911</p> <p>Date Issued: 25/11/2021</p> <p>A/C Registration / SN: 9M-BOB/11212</p> <p>Sheet: 1 of 1</p>
---	---

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	PHYSICAL INSPECTION FOR CHECKING APPLICABILITY OF TMI NO. 109-533 NEW ISSUE TO CONFIRM THE GPS RECEIVERS P/N: 81440-32-241Q OR P/N: 81440-42-241Q EITHER FITTED ON AIRCRAFT OR NOT	TMI NO. 109-533, NEW ISSUE TIC-A109E-21-0090	<u>10</u> (PLEASE ADVISE)

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.
Best Regards,

Zaty Nadhira Mohamed Zuhari
Continuing Airworthiness Management Manager
Email: zaty@galaxyaerospace.my



CLIENT/OWNER: FIRE AND RESCUE DEPT. OF MALAYSIA AIRCRAFT TYPE: A109E REGISTRATION: 9M-BOB BASE/FACILITY: 27422 MIA T DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO: 8911-001 WORK/INSP/DESC: PHYSICAL INSPECTION WORKPACK REF: 9M-BOB-8911 AJL REF NO.: REFER WORKPACK SHEET: 1 OF 1
	AIRCRAFT	11212	REFER WORKPACK		
	#1 ENGINE:	PCE-BC0308	REFER WORKPACK		
	#2 ENGINE:	PCE-BC0358	REFER WORKPACK		
			NG / N1	NF / N2	

Reason for raising: PHYSICAL INSPECTION FOR CHECKING APPLICABILITY OF TMI NO. 109-533 NEW ISSUE TO BE CARRIED OUT IN ACCORDANCE WITH TMI NO. 109-533, NEW ISSUE A109E IETP - 32ND ISSUE: 2021-09-15 OR LATEST APPROVED REVISION PHYSICAL INSPECTION FOR CHECKING APPLICABILITY OF TMI NO. 109-533 NEW ISSUE	Raised by and date: Muhammad Ihsan Masri 25/11/2021	Other requirements/information: NIL
--	---	--

Item	Description	Technician	* Eng. CRS	Date
1	PHYSICAL INSPECTION TO BE CARRY OUT DUE TO CHECK THE APPLICABILTY OF THE GPS RECEIVERS PART NUMBER PART NUMBER: 81440-02-241M SERIAL NUMBER: 2100806 REFERENCE: TMI NO. 109-533, NEW ISSUE REMARKS: C/OUT SATISFACTORY.	H.	Keritt. 	27/1/22

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK WHERE APPLICABLE

PARTS ORDERED	DD RETED	DUPICAR INF	GROUND RUN	TESTED	ENGINE OIL	ADDITIONAL WORKSHEET	UNDISCOVERED DEFECT	PLANNING FORECAST	DDRY UPDATE	STATUS UPDATE	DD STATUS	AIRCRAFT IDENTITY	ENGINEER BOOK	PROPELLER LOG BOOK	LOG CARD	SEMICONP LOG CARD	W/O RECORD BOOK
---------------	----------	-------------	------------	--------	------------	----------------------	---------------------	-------------------	-------------	---------------	-----------	-------------------	---------------	--------------------	----------	-------------------	-----------------



CLIENT/OWNER: FIRE AND RESCUE DEPT. OF MALAYSIA AIRCRAFT TYPE: A109E REGISTRATION: 9M-BOB BASE/FACILITY: MAT DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET NO:	8911-001
	AIRCRAFT	11212	REFER WORKPACK	WORK/INSP/DESC:	PHYSICAL INSPECTION
	#1 ENGINE:	PCE-BC0308	REFER WORKPACK	WORKPACK REF:	9M-BOB-8911
	#2 ENGINE:	PCE-BC0358	REFER WORKPACK	AJL REF NO.:	REFER WORKPACK
			NG / N1	NF / N2	SHEET: 1 OF 1

REASON FOR RAISING: PHYSICAL INSPECTION FOR CHECKING APPLICABILITY OF TMI NO. 109-533 NEW ISSUE TO BE CARRIED OUT IN ACCORDANCE WITH TMI NO. 109-533, NEW ISSUE A109E IETP - 32ND ISSUE: 2021-09-15 OR LATEST APPROVED REVISION	Raised by and date: Muhammad Ihsan Masri 25/11/2021	Other requirements/information: NIL
---	---	--

Item	Part No	Description	Serial Number		Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX	Release Reference
			Off	On					
<i>(Table content is crossed out with a diagonal line)</i>									

NAME	FIRM	SIGN & APPROVAL	DATE
ADZRAEI HASIFF	GAM	<i>(Signature)</i>	27/1/22

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK WHERE APPLICABLE

WORKSHEET'S RETURNED	RD. RETEN.	DUPPLICATE INSP	CHECKED IN/A	FLIGHTS	TURBO CH.	ADDITIONAL WORK SHEET	WORKSHOP DEFECT	PLANNED WORKSHEET	EMPTY UP/DOWN	STATUS UPDATE	STD. VALUE	AIRCRAFT WORKSHOP	ENGINE LOG SHEET	PROPELLER LOGBOOK	LX (CARD)	GEN/TAMP LOGBOOK	LOG/RELEASE BOOK
----------------------	------------	-----------------	--------------	---------	-----------	-----------------------	-----------------	-------------------	---------------	---------------	------------	-------------------	------------------	-------------------	-----------	------------------	------------------