

## COMPONENT RECORD

Phone (310) 539-0508 Fax (310) 539-5198

## **COMPONENT RECORD**

					No. 10 April 1990 Apri
Part Number	Description	Serial Number	Date of Manufacture	Maximum Service Life	Overhaul Interval
D224-4	Tail Rotor Driveshaft Assy	11224	N/A	N/A	2000 Hours

Date	Helicopter Model	Helicopter Serial Number	Helicopter Time in Service	Component Time Since New or Overhaul	Action		Remarks
11/MAY/2023	R66	1256	0.00 Hours	Now	REMOVAL	MAINTENANCE	
					INSTALLATION	OTHER	
					REMOVAL	MAINTENANCE	
					INSTALLATION	OTHER	
					REMOVAL	MAINTENANCE	
					INSTALLATION	OTHER	
					REMOVAL	MAINTENANCE	
					INSTALLATION	OTHER	
					REMOVAL	MAINTENANCE	
					INSTALLATION	OTHER	
					REMOVAL	MAINTENANCE	
					INSTALLATION	OTHER	
					REMOVAL	MAINTENANCE	
					INSTALLATION	OTHER	
					REMOVAL	MAINTENANCE	
					INSTALLATION	OTHER	
					REMOVAL	MAINTENANCE	
					INSTALLATION	OTHER	
					REMOVAL	MAINTENANCE	
					INSTALLATION	OTHER	
					REMOVAL	MAINTENANCE	
					INSTALLATION	OTHER	
					REMOVAL	MAINTENANCE	
					INSTALLATION	OTHER	
					REMOVAL	MAINTENANCE	
					INSTALLATION		
					REMOVAL	MAINTENANCE	
					INSTALLATION		
					REMOVAL	MAINTENANCE	
					INSTALLATION		
					REMOVAL	MAINTENANCE	
					INSTALLATION	OTHER	