

LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

COMPONENTS INSTALLED ON ASSY

ASSY P/N (26)

3G5350A00136

ASSY S/N (27)

PZL070

COMPONENT DATA

INSTALLATION

REMOVAL

DESCRIPTION (28)	P/N (29)	MANUFACTURING DATE (31)	ASSY				COMPONENT				REMOVAL								
			TOTAL HOURS (33)	TOTAL HOURS (34)	TIME SINCE OH (35)	DATE (36)	TOTAL HOURS (38)	TOTAL HOURS (39)	TOTAL HOURS WITH PENALTY FACTOR (40)	TIME SINCE OH (41)	DATE (42)								
			TOTAL LANDINGS (33)	TOTAL LANDINGS (34)	LANDINGS SINCE OH (35)	STAMP AND SIGNATURE (37)	TOTAL LANDINGS (38)	TOTAL LANDINGS (39)	TOTAL LANDINGS WITH PENALTY FACTOR (40)	LANDINGS SINCE OH (41)	STAMP AND SIGNATURE (43)								
B/N (30)	RETIREMENT LIFE / TIME LIMITS (32)	TOTAL LIFTS/CYCLES (33)	TOTAL LIFTS/CYCLES (34)	LIFTS/CYCLES SINCE OH (35)		TOTAL LIFTS/CYCLES (38)	TOTAL LIFTS/CYCLES (39)	TOTAL LIFTS/CYCLES SINCE OH (41)											
ASSY FIN	3G5351A00136	01/2017	00.00	00.00	NEW	03/2017													
	PZL070	ON CONDITION																	
T. G. B. FITTING	3G5351A01152	01/2017	00.00	00.00	NEW	03/2017													
	0069PZL	7200 FH																	
ATTACH. FITTING ON FIN UPPER LH	3G5351A08931	01/2017	00.00	00.00	NEW	03/2017													
	0068PZL	7600 FH																	
ATTACH. FITTING ON FIN UPPER RH	3G5351A09031	01/2017	00.00	00.00	NEW	03/2017													
	0072PZL	7600 FH																	
ATTACH. FITTING ON FIN LOWER	3G5351A09131	01/2017	00.00	00.00	NEW	03/2017													
	0114PZL	10600 FH																	