

Section 04-30 Certification Maintenance Requirements Table 2 Certification maintenancerequirements

Aeronet Galaxy Aerospace > Modifications > Update - Google Chrome

galaxyaerospace.aeronet.nz/index.html

INSPECTION ID: 627 Close Update Save & Close

General | Config List | Aircraft List | Task List | ATA History | Linked To | BOM | Special Tasks

Inspection Type: Airframe Inspection

Title/Subject: AF 2400 FH INSPECTION

Reference/Number: AMPI 89-A-04-30-00

Version No:

Details/Instructions: AF 2400 FH INSPECTION TO BE CARRIED OUT IAW MAINT:
IETP AW189, 14th Issue: 2018-02-02, Updated: 2018-03-16

URL:

Date: -- -- --

Tolerance: 0 % (Whole numbers only)

INSPECTION ID: 627 Close Update Save & Close

General | Config List | Aircraft List | Task List | ATA History | Linked To | BOM | Special Tasks

| | Task# | Job# | Title | Budget/Actual | Average | Priority | |
|--|---------|------|-----------------------------|---------------|---------|--------------------------------|--|
| | 7465 ▶ | - | CM32-01 LANDING GEAR | 0.00 | 0.00 | <input type="text" value="1"/> | |
| | 11985 ▶ | - | CM71-02 ENGINE INSTALLATION | 0.00 | 0.00 | <input type="text" value="2"/> | |
| | 23792 ▶ | - | ENGINE INSTALLATION | 0.00 | 0.00 | <input type="text" value="3"/> | |

Section 05-21 Maintenance task overview - General Table 2 Maintenance tasks overview

1. 52-08

Task #: 18001 Created: 20/02/2019 Modified: 24/11/2021 Template ID: 11892 Save to template Close Up

General Accounts Production Time Allocations Documents ATA List History

| | | | |
|-------------------------|---|---------------|----------------------------------|
| Task Number : | 0 | Task ID : | 18001 |
| Job : | 0 #0 - Search | Parent : | 0 Search |
| Start Date : | 20 02 2019 | Created By : | Continuing Airworthiness Manager |
| Due Date : | 22 02 2019 | Modified By : | CAMO JBPM |
| Defects/Title : | 52-08 DETAILED INSPECTION OF THE VISIBLE PART OF LH/RH COCKPIT DOOR LOWER HINGE ASSY | Priority : | Low |
| Reference/AIW : | | Status : | WIP |
| | | Category : | |
| Details/Rectification : | 52-08 DETAILED INSPECTION OF THE VISIBLE PART OF LH/RH COCKPIT DOOR LOWER HINGE ASSY NOTE 58 INSPECTION TASK SCHEDULE IS PART OF THE MANUFACTURER BASELINE CPCP. WITH REFERENCE TO MRBR 189G0000M006, THE OPERATOR IS REQUESTED TO REPORT TO MANUFACTURER LEVEL 1 CORROSION FINDINGS, AND TO MANUFACTURER AND TO THE NATIONAL AVIATION AUTHORITY ALL LEVEL 2 OR 3 CORROSION FINDINGS, PROVIDING THE SPECIFIED INFORMATION WITHIN MRBR APPENDIX 8 PERFORM A DETAILED INSPECTION FOR CONDITION, DAMAGE AND CORROSION ON THE LH/RH LOWER HINGES. REFERENCES (DMC): 89-A-52-11-00-03A-31AA-A MRBR TASK ID: 521103S-01 REMARKS: | | |
| Notes : | | | |

2. 63-31

INSPECTION ID: 4442 Close Update Save & Close

General Config List Aircraft List Task List ATA History Linked To BOM Special Tasks

Inspection Type: Special Inspections

Title/Subject: AT EACH MGB OIL COOLER SILENCED EXHAUST DUCT REMOVAL

Reference/Number: 89-A-63-20-01-00A-720A-A

INSPECTION ID: 4442 Close Update Save & Close

General Config List Aircraft List Task List ATA History Linked To BOM Special Tasks

| @ | Aircraft | Based On | Period | Warning Unit | Warning | Last Done | Next Due | |
|---|----------|--------------|--------|--------------|---------|-----------|----------|--|
| | 9M-BOE | On Condition | 0 | | 0 | 0.00 | 0.00 | |
| | 9M-BOF | On Condition | 0 | | 0 | 0.00 | 0.00 | |

Defects/Title : 63-31 RESTORATION (CLEANING) OF THE FOAM CONTAINED IN THE OIL

Priority : Low

Status : WIP

Reference/IAW :

Category :

Details/Rectification : CLEAN THE OIL COOLER DUCT FOAM TO PREVENT MOISTURE OR CONTAMINATS ACCUMULATION
 REFERENCE: 89-A-63-20-01-00A-720A-A
 REMARKS: