

TIC-AW139-21-0300

AD NO. 2015-0155, NEW ISSUE re-evaluate

ATA 30 - ICE AND RAIN PROTECTION - FULL ICE PROTECTION SYSTEM TAIL ROTOR SLIP RING - INSPECTION / REPLACEMENT

AD/SB ID: 3811 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: ADS Repetitive

Reference/Number: ICE AND RAIN PROTECTION - FULL ICE PROTECTION SYSTEM
TAIL ROTOR SLIP RING - INSPECTION / REPLACEMENT

Title/Subject: EASA AD 2015-0155, NEW ISSUE

Version No:

Reason For Raising:

URL:

















Date: -- -- --

Tolerance: 0 % (Whole numbers only)

Creep Type: No Creep

Document	Title	Filename
No Documents currently linked to the inspection		

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-PMA	Date (Days)	-	Days	0	-	-	NOT APPLICABLE	
	9M-PMB	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMD	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PME	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMF	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-YPG	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-YTL	Not Applicable	-		0	-	-	NOT APPLICABLE	