"DELIVERY NOTE WP



DELIVER TO:

GALAXY AEROSPACE (M) SDN. BHD. **CAMO DEPARTMENT** Lot 11, MRO Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor Malaysia.

Attn: Zaty Nadhira binti Mohamed Zuhari

DN NUMBER: GAM/DN/23/144

OUR REFERENCE: UMC-BOB-23-013

WO REFERENCE: -

DATE COMPLETION: 18 SEPT 2023

AJL NUMBER: 000122

A/C TYPE A		W139	A/C REG			9M-BOB			A/C S/N	11212				
		ND RESCUE F MALAYSIA	A/C TOTAL TII			3846:27		LANDINGS			4454			
ENGINE #1 S/N PCE-		-BC0308	T.S.N		1071:17			T.S.O			-			
ENGINE #2 S/N PCE-		BC0358	T.S.N			3049:57		T.S.O			-			
LICT OF TACKS DEPENDANCE		WP				NUMBER OF PAGES								
LIST OF TASKS PERFORMED			NUMBER	*WS	*PR		*TR		*ARC	*5	*SBC		*ОТН	
FOUND SCISSOR ATTACHMENT BUSHING WORN AND CHIPPING ON SLEEVE ASSY			-001	1	1		1	1		1		-	-	
*THIS IS TO CER	TIFY TH	HAT TASKS	LISTED ABOVE H	AAS BEEN ACC	OMPL	ISHE	D AS PER PO	/wc	ORK ORDE	R/SERVICE OR	DERI	NO. 1AS AI	BOVE.	
NAME NURUL AN			ЛIRA	SIGNA	ATURE		Mi		DATE		02 OCT 2023			
VERIFIED AND ACCEPTED BY							NUR HUSNINA BINTI MUHAMAD ZURAIDI CAMO Planner Galaxy Aerospace (M) Sdn Bhd (1040262-D)							
DATE								0 6 OCT 2023						
*WS – WORKS	HEET	<u> </u>		*S – SERVI	CEAB	LE LA	ABFL							

A/C DETAILS

*WS – WORKSHEET

*S – SERVICEABLE LABEL

*PR - PART REPORT

*SBC - SERVICE BULLETIN COMPLIANCE

*ARC – AUTHORISED RELEASE CERTIFICATE *OTH – OTHERS

Page: 1 GAM/E-015



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D] Suite 11-14. Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax. +603 7734 7526 el: +603 7734 7226 | Fax: +603 7734 7526 ww.galaxyaerospace.my | enquiry@galaxyaerospace.my



CLIENT/OWNER: JABATAN BOMBA DAN WORKSHEET NO: SERIAL NO. HOURS LDG/CYCLE UMC-BOB-23- 013 PENYELAMAT MALAYSIA WORK/INSP/DESC: **AIRCRAFT** 11212 3846:27 4454 DEFECT AIRCRAFT TYPE: A109E WORKPACK REF: NOT APPLICABLE #1 ENGINE: PCE-BC0308 1071:17 REGISTRATION: 9M-BOB AJL REF NO.: OOO 122 #2 ENGINE: PCE-BC0358 3049:57 BASE/FACILITY: MIAT DATE IN: 18-9-23 OUT: 18-9-23 NG / N1 NF / N2 Reason for raising: FOUND SCISSOR ATTACHMENT Raised by and date: Other requirements/information: BUSHING WORN AND CHIPPING HAS1 FF NIL 18/9/23 OH SUBER ASSY SLEEVE ASSY. Description Technician * Eng. CRS Item Date CARRIED OUT REPLACEMENT OF SLEEVE 1. 18-9-23 ASSY AS PER A 109E 16TP 34+4 155UE 2023-06-86 UPDATED 2023-09-08 MM 64-31-6 FOUND SATISFACTORY. * FOR INDEPENDENT INSPECTION AND TAIL ROTOR HUB AND BLADE ASSEMBLY INSTALLATION REFER 9M-BOB-16715. Galaxy Aerospace (M) Sdn. Bhd. I hereby certify the following task has been performed and found satisfactory: 1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan. 4) FOD check has been done. Sign & Stamp: //went Date & Time: 18.9.23 *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work MMO/2016/02 the aircraft / aircraft component is considered ready for release to service. *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with and in respect to that work the aircraft / aircraft component is considered ready for release to service. TICK ✓ WHERE APPLICABLE



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my

PARTS REPORT



CLIENT/OWNER: JABATAN BOMBA DAN SERIAL NO. HOURS LDG/CYCLE WORKSHEET NO: UMC-BOB-23- 612 PENYELAMAT MALAYSIA 11212 REFER WORKPACK WORK/INSP/DESC: REPLACEMENT AIRCRAFT AIRCRAFT TYPE: A109E PCE-BC0308 REFER WORKPACK NOT APPLICABLE WORKPACK REF: #1 ENGINE: REGISTRATION: 9M-BOB BASE/FACILITY: MI AT PCE-BC0358 AJL REF NO .: 000122 REFER WORKPACK #2 ENGINE: OUT: 18-9.73 1 DATE IN: SHEET: OF NG/N1 NF/N2 REASON FOR RAISING: FOUND SCISSOR ATTACHMENT Raised by and date: Other requirements/information: BUSHIMA WORN AND CHIPPING HASIPF NIL OH SLEEVE ASSY. 18/9/23 Lifed Item Information Part No Item Description Position Reason Release Reference TSN/TSO/DUE/TIMEX Off 109-0130 SLEEVE ASSY WORN 61351 547272 TR 900298 1 90-121 FIRM SIGN & APPROVAL ADZRAGI HASIFF GAM 18.9.2023 😡 *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. MO/2016/02 *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with and in respect to that work the aircraft / aircraft component is considered ready for release to service. ☐ TICK ✓ WHERE APPLICABLE



GALAXY AEROSPACE (M) SDN, BHD. [1040262-D]
Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre,
Suitan Abdul Aziz Shah Airport. 47200 Subang, Selangor, Maleysia.
T£i: +603 7734 7226 | Fax: +603 7734 7526
www.galaxyaerospace.my | enquiry@galaxyaerospace.my


Tools Report



11212 Work Pack No: UMC - BOB - 23 - 013 Aircraft Serial No: Aircraft Type: A109E DESC: REPLACEMENT Aircraft Reg: 9M-BOB PAGE: Of Worksheet Ref No. / Description Part No **Serial Number Calibration Due Date** Item No.

JAA form O	Name of the last	15 0	14. Ce	13. Remarks	00033					000019	o. Item		į	of J	Autority E.N.A
ne - Issue 4 (1014)	EDVISOR OF STATE OF S	Approved design data and are in condition for safe operation non-approved design data specified in block 13	Certifies that the items identified above were manufactured in conformity to-		BEARING, SLEEVE WASHER WASHER	BEARING BOOT	REAR HALF-SCISSOR ASSY FRONT HALF-SCISSOR	SPACER TAIL ROTOR SLEEVE ASSY	BOOT, DUST AND MSTRE SEAL	LOCK WASHER ROCKER ARM ASSY WASHER	7. Description		Summabul Halle and Addiess.	of JAA (ITALY)	Autority / Country E.N.A.C. a member
Date (4) 104/2003	D the	condition for safe operation ed in block 13	e manufactured in conformics to:		109-0130-98-101/ 109-0131-19-3/ 109-0131-25-1/ 109-0131-25-5/	109-0130-95-103/	109-0130 109-0130 109-0130	109-0130-89-10	109-0130-82-1 109-0130-83-3	-0130-	8. Part. No.	AN AGUNTANATURA COLUMBATA	400	JAA FORM ONE	AUTHORIZED RELEASE
22. Name 23. Date (d/m/) (*) Installer must cross-check eligibility with applicable technical data	20. Authorised Signature	Certifies that unless otherwise specified described in block 13, was accomplist to that work the items are considered r			A109 A109 A109 A109	A109 A109	A109 A109	A109 A109	A109 A109	A109 A109	9. Eligibility(*)	NO COMPANY	SP	NE CONTRACTOR	CERTIFICATE
ibility with		elease to Ser herwise spec 3, was accon			2,000	1,00			2,00	2,00	10. Q.ty		٠,		
23. Date (d/m/y) applicable technical data	21. Cortific.	Other r. Certifies that unless otherwise specified in block 13. Are work ide described in block 13, was accomplished in accordance with 1 to that work the items are considered ready for release to service.	PAG.		N.A. N.A.	N.A.	C5001 N.A.	H b	N.A.	N.A. N.A.	11. Serial/Batch No	R.	5. 1	***********	3. /
2	21. Certificate/Approval Ref. No. RAI - 221	Other regulation specified in block 13. Are work identified in block 13 and described in block 13, was accomplished in accordance with JAR 145 and in respect to that work the items are considered ready for release to service.	G. 3 DI PAG. 11		INSPECTED/TESTED INSPECTED/TESTED MANUFACTURED MANUFACTURED MANUFACTURED	MANUFACTURED INSPECTED/TESTED	MANUFACTURED MANUFACTURED MANUFACTURED		MANUFACTURED INSPECTED/TESTED	MANUFACTURED TNS DECTED / TESTED	Vo. 12. Status/Work	RIF. PACK.L. N. 0124782	5. Work Order/Contract/Invoice	AGU2003-11394/D	3. Form Tracking Number

...



SERVICEABLE	Galaxy Aerospace**
DESCRIPTION : TAIL POTOR SLE	EVE ASSY
PARTNO. : 109 - 6130 - 90-	121 OTY: 2 ER
SERIAL NO. : J 47271 , J473	272
STATUS : OVH/REPAIR/MOD/CALF	FEST/NEW/CONSUMABLE/OSE
TSN : NIA TS	O: NIA
SHELF DUE/EXP DATE : NIA	
INSPECTED BY: MUKARRAMAH	GiN/ID. NO:
(SERO)	900298
SIGN : DATE : 25/02/24	
	GAM/E-005

Certified Frue Copy of the Original

Oty: 1
Signature: Date: 12 9 23
Galaxy Aerospace (M) Sdn. Bhd.

FLT. NO. 3 FLT. NO "MR STATEMENT DATE 3 3 찎 FIGHT M BMPC-808-23-002 AND CXIPPING OH SUCENE ASSY. FOUND SCISSOR ATTACHMENT BUSHING WORK HIOM IF LOW OBJ- JOBO 954 9202 · K·13 24 MONTHS INSP COMPLIANCE DUE PLOT 도 C THE WORK RECORDED ABOVE HAS BEEN CARRIED OUT IN ACCORDANCE WITH THE REQUIREMENTS OF THE MCAR FOR THE TIME BEING IN FORCE AND IN THAT RESPECT THE AIRCRAFT/EQUIPMENT IS CONSIDERED FIT FOR RELEASE TO SERVICE. CLIEN FUEL UPLIFT Q G RECORD OF DEFECT(S). ENTER 'NIL' IF NO DEFECT FOUND マエマ ₹ \$ RATOR CO-PILOT ヱ FROM 도 FUEL DEPART 딢 NSP ヱ ಠ ه ک TOTAL CARRY FORWARD TAKE OFF DEPART TOTAL BEFORE FLIGHT 3846:277 AIRCRAFT ENGINE TYPE FUEL TOTAL TOTAL THIS PAGE 2060 A109E 5 ARRIVAL <u>ر</u> س NEXT CALENDAR INSP LDG IME ۹ スローアナルスタスへの the the March JA JITOL 900 ENG 1 PILOT / ENGINEER とって TOTALFLT ENG OIL UPLIFT **AMO/2016/02** J ENG 2 4454 LANDING 子口へ AIRCRAFT SERIAL NUMBER 1400 14,00 GEARBOX TIME MAN 1 W 9751 45:6408 21:160 ENG 1 んしん OIL UPLIFI NO. ITEM ح_ 2 **ENGINE HOURS** 808 NSP 띪 TAIL 6 ST DAILY CHECK HAS BEEN CARRIED OUT I.A.W APPLICABLE SLEEVE ASSY REPURED AS PER APPROVED MAINTENANCE PROGRAMME. REFUR 9M-808-16963 LMC-808-23-013 FOUND SATISFACTORY CARPICO OUT ALLO COMPLIGO SANGFACIONA ENG 2 ENG 1 LINAN NO OAH D T ENG 1 ENG 2 FUEL RECTIFICATION(S) TAKEN ENG CYCLE 9 3((5 マキ MEASURING UNITS دی ف ENG 2 SIGN (760 404 HOURS HTUA 의증 CARGO HOOK 0 CYCLE TIME O (FORM NO: GAM/C-008/A109E Rev 0 (12/21) PAGE SERIAL NO: 000122SalaxyAerospace 1ST COPY: CAMO TECHNICAL RECORD MR SIGN** APPROVAL NO: CAMO/2016/03 SIGN AIRCRAFT JOURNEY LOG HOURS O 声 V **HOIST** HTU 83 CYCLE Steac 1631 18-9-2023 DATE TIME