

WORK ORDER

To: AGUSTA WESTLAND MALAYSIA SDN BHD

Address: LOT 1 & 2, HELICOPTER CENTER
 SULTAN ABDUL AZIZ SHAH AIRPORT
 SUBANG, Malaysia

Attention: Nur Suzana Noor
 Production Planning & Technical Records
 Manager
 nursuzana.noor@leonardocompany.com

Work Order Number: GAM-WO-18-356

Work Pack Reference: WP-PMA-18-356

Date Issued: 07/11/2018

A/C Registration / SN: 9M-PMA/31807

Sheet: 1 of 1

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	BT 139-358 REV.A ATA 71 - EXHAUST DUCTS AND REAR FIREWALL RETROMOD (OPTIONAL SB) REQUIRE PHYSICAL CHECK ON THE PN AND SN (IF APPLICABLE) AS PER WORKSHEET	BT 139-358 REV.A	8 (PLEASE ADVISE)

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.
 Best Regards,



Hazrin Sani
 Continuing Airworthiness Manager
 Email: hazrin@galaxyaerospace.my

CLIENT/OWNER:	SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET NO:	WP-PMA-18-356-001
AIRCRAFT TYPE: AW139	AIRCRAFT	14:40	28	WORK/INSP/DESC:	BT 139-358
REGISTRATION: 9M-PMA	#1 ENGINE:	14:40		WORKPACK REF:	WP-PMA-18-356
BASE/FACILITY: WMSA	#2 ENGINE:	14:40		LBE REF NO.:	
DATE IN: 2/11/18 OUT: 13/11/18			NG / N1	NF / N2	SHEET: 1 OF 1

Reason for raising: BT 139-358 ATA 71 - EXHAUST DUCTS AND REAR FIREWALL RETROMOD PHYSICAL CHECK REQUIRED.	Raised by and date: AZLIZAN 07/11/2018	Other requirements/information: N/A
---	--	--

Item	Description	Technician	* Eng. CRS	Date
1	<p>SB139-358 REV.A (OPTIONAL SB)</p> <p>REQUIRED PHYSICAL CHECK TO CLARIFY EXHAUST PN FITTED ON AIRCRAFT</p> <p>PHYSICAL CHECK CARRIED OUT AS PER BELOW DETAILS:</p> <p>A. LH FWD EXHAUST PN: <u>3G7810A00331</u> SN: <u>CUR 00452</u> (IF APPLICABLE)</p> <p>B. LH REAR EJECTOR PN: <u>3G7810A02131</u> SN: <u>NOT VISIBLE</u> (IF APPLICABLE)</p> <p>C. RH FWD EXHAUST PN: <u>3G7810A00231</u> SN: <u>CUR 00615</u> (IF APPLICABLE)</p> <p>D. RH REAR EJECTOR PN: <u>3G7810A02231</u> SN: <u>CUR 00695</u> (IF APPLICABLE)</p> <p>E. TUNNEL ASSY PN: <u>3G7130A13214A</u> SN: <u>CUR 00129</u> (IF APPLICABLE)</p> <p>F. REAR FIREWALL MODULE ASSY. RH PN: <u>3G7810A02623A</u> SN: <u>-</u> (IF APPLICABLE) LH PN: <u>3G7810A02532A</u> SN: <u>CUR 00161</u> REF: AS PER BT 139-358</p> <p>REMARK: <u>FOUND SATISFACTORY</u></p>	<i>[Signature]</i>		30.11.18

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK ✓ WHERE APPLICABLE

PARTS LABELED & RETURNED	D.D. RAISED	DUPLICATE INSP.	GROUND RUN	FLIGHT TEST	TORQUE CHK.	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	D.D. STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	OEM/COMP LOG CARD	MOD.RECORD BOOK
--------------------------------	----------------	--------------------	---------------	-------------	----------------	-------------------------	---------------------	----------------------	-----------------	------------------	----------------	----------------------	--------------------	-----------------------	-------------	----------------------	--------------------

Please send to the following address: LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988	SERVICE BULLETIN COMPLIANCE FORM	Date: 30/11/2018
	Number: BT 139-358	
	Revision: REV. A.	

Customer Name and Address: GALAXY AEROSPACE MALAYSIA INTERNATIONAL AEROSPACE CENTRE. SULTAN ABDUL AZIZ SHAH AIRPORT 47200 SUDANG.	Telephone: 03-7734 7226
	Fax: 03-7734 7226
	B.T. Compliance Date: 30/11/2018

Helicopter Model	S/N	Total Number	Total Hours	T.S.O.
AW 139	31807	01	17:35	N/A

Remarks: PHYSICAL INSPECTION C/OWT
 FOUND DATS.
 REF ATTACHMENT FOR ITEMS PN 9 SN.

Information:

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.