## SECTION 1.0 AIRWORTHINESS DIRECTIVES (AIRFRAME) COMPLIANCE SUMMARY

Aircraft Type: A\$365N3 Aircraft S/N: 6835

Registration:	9M-TSV					Last Reviewed:	10-Jun-24
No. Authority	AD Reference	Effective Date	Description	Applicability	Corresponding SB	Status	Compliance
1	F-1998-324-045	22/08/1998	Monitoring of MGB vibration level before MOD 0731B21	No	31.00.03	Closed	N/A. Mod 0731B21 embodied at production. Refer Individual Inspection Log Book.
2	F-1998-384-047	3/10/1998	Check Torque of Sleeves pins / Spherical thrust-bearing	Yes	05.00.39	Closed	Complied. Note: Task already incorporated into the ALS CHAP. 04
		<u> </u>	AlliedSignal Aerospace Transponder Equipment P/N 066.1062.00				
3	F-1998-446-IMP	18/11/1998	/10/02	No	Nil	Closed	N/A. P/N 066-01143-2101 installed on aircraft. Refer Individual Inspection Log Book
4	F-1998-517-048 R2	23/12/2000	Power Loss Board – Operating check for aircraft before mod 0771B84 and 0771B86	No	05.00.40 R1	Closed	N/A. Mod 0771B84 and 0771B86 embodied. Refer Individual Inspection Log Book
						5.0.00	, , , , , , , , , , , , , , , , , , ,
5	F-1999-035-IMP R1	5/1/2000	Safety belts type "Aircraft belts INC" P/N 343-1.	No	Nil	Closed	N/A. AM SAFE P/N AFG 0313670 (Pilot & Co-Pilot); VIP Seat Fwd LH & RH P/N 504808-343-2251 and VIP Seat Rear P/N 502288-403-2251 installed on aircraft.
			BF Goodrich avionics systems storm scope Check antenna				
6	F-1999-297-IMP	7/8/1999	installation	No	S/B B.F 78-A	Closed	N/A. Equipment not installed. Refer Individual Inspection Log Book; AD Section Page 6 of 10.
7	F-1999-459-049 R1	24/06/2000	To prevent loss in flight check Non jettison panel, on enlarged sliding door	No	01.00.49	Closed	N/A. Aircraft delivered after 11/99.Refer Individual Inspection Log Book
8	F-2000-108-050 R2	15/09/2001	Check no crack on sand-filters	No	71.00.14.R2	Closed	N/A Sand- filter not installed.
9	F-2000-302	12/7/2000	Check bonding Ferry fuel tank	No	28.00.28	Closed	N/A. Fuel Tank not installed.
			Modification Software Engine indicating before Mod 0771B84				
10	F-2000-517-051	23/12/2000	and 0771B86	No	01.00.52	Closed	N/A Mod 0771B84 and 0771B86 embodied at production.
11	F-2001-023 R2	2/2/2002	Check power transmission VHF navigation system	Yes	Nil	Closed	C/W by manufacturer. Refer Individual Inspection Log Book; AD Section Page 6 of 10.
		2, 2, 2 2 2					
12	F-2001-060-052	3/3/2001	Check cracks on Fuselage - 9° frame - Reinforced latch support	No	53.00.42	Closed	N/A A/C delivered after 10/2000.
13	F-2001-061-053	3/3/2001	Check Cracks on Fuselage - 9° frame- Stretcher support	No	53.00.43	Closed	N/A. A/C delivered after 01/2001. Refer Individual Inspection Log Book
10	1 2001 001 000	0/0/2001	AD cancelled and	140	AD cancelled and	Closed	AD cancelled and
14	F-2001-318 R1	25/07/2001	superseded AD EU 2009-0122	No	superseded AD EU 2009-0122	Superseded	superseded AD EU 2009-0122
1.5	5 0001 500 H ID	10/11/0001	Check power transmission of VHF NAV VN 411B Type. AlliedSigna		0.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 + 10.00 +	a	
15	F-2001-520-IMP	10/11/2001	INC.	No	S/B Allied signal VN-411B21 Sicma	Closed	N/A. P/N 066-01066-0025 installed. Refer Individual Inspection Log Book
16	F-2001-605	12/12/2001	Check for cracks on Passengers seats fitting. (Backrest links).	No	90-25-012R3	Closed	N/A. Equipment not installed. Refer Individual Inspection Log Book; AD Section Page 7 of 10.
17	F-2002-044	23/01/2002	Check installation on Siren release P/N AS215-7	No	05.00.41	Closed	N/A. Equipment not installed. Refer Individual Inspection Log Book; AD Section Page 7 of 10.
18	F-2002-104 R2	2/2/2002	Check safety belts and restraint System .Anjou Aeronaut. P/N 343-1	No	S/B Anjou 343-1-25-01	Closed	N/A due AM SAFE Model type installed. Refer Individual Inspection Log Book
.0	T ZOOZ TO TRZ	2,2,2002		110	S/B Anjou	0.0300	Ty/ Case / William E model Type will called a Model will pool for being book
19	F-2002-105 R2	2/2/2002	Check Safety belts and restraint System . Anjou Aeronaut.	No	343-1-25-02	Closed	N/A due AMSAFE Model type installed. Refer Individual Inspection Log Book
00	F 0000 075 ILID 23	0.44,0000	Check Transponder Mode S TDR-94 and TDR-94DP/ P/N 622-	Nie	Rockwell	Class d	N/A Towns and a Mark CDANOV 011/0 0101 and the distribution of the
20	F-2002-275-IMP R1	8/6/2002	9352-004  Check Torque MGB. Assembly studs tightening before MOD	No	s/b 17	Closed	N/A. Transponder Mode S P/N 066-01143-2101 installed. Refer Individual Inspection Log Book
21	F-2002-285-055 R1	5/7/2003	0763B76	No	05.00.42	Closed	N/A. Mod 0763B76 embodied at production. Refer Individual Inspection Log Book
			Check conformity "TRW-SAMM" main servo controls overhauled				
22	F-2002-312-056 R1	20/12/2003	or repair	No	67.00.08	Closed	N/A. All servo controls fitted on aircraft are new. (D.O.M Year 2008).
23	F-2002-323-IMP	6/6/2002	Mode C 621A-3 transponder (P/N 522-2703-XXX)	No	Rockwell 621A-3-34-21R1	Closed	N/A. Transponder Mode S P/N 066-01143-2101 installed.
20	. 2002 020 11411	0, 0, 2002		.10	02.7.0 04 ZIKI	0.0300	
			Correction of operating Hours on main rotor drive and				
24	F-2002-452 R1	10/5/2003	transmission assembly for aircraft delivered before 13/08/2002	No	62.00.19	Closed	N/A for aircraft delivered after 8/2002. Refer Individual Inspection Log Book; AD Section Page 9 of 10.
25	F-2002-472-057	18/09/2002	Tail rotor head Remove and discard Pitch change control rod before MOD 0765B41	No	01.00.55	Closed	N/A. Mod 0765B41 embodied at production. Refer Individual Inspection Log Book
20	. 2002 4/2 00/	10,07,2002		.10	000.00	0.0304	The state of the s