



## ASSEMBLY HISTORICAL RECORD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED

65

CHAP. N° .....

PART. ....

ASSEMBLY NAME **TAIL ROTOR GEAR BOX 90°** PART. N° **109-0440-01-121** SERIAL N° **J23856** ASSEMBLY DATE **Apr. 02** RETIREMENT LIFE **(3000 OH)** (HOURS)

### INSTALLATION

### REMOVAL

Due  
4485.80

DATE	INSTALLED ON A/C		ACTIVITY	A/C TOTAL TIME	ASSY LIFE		SIGNATURE	DATE	A/C TOTAL TIME	ASSY LIFE		REASON OF REMOVAL
	BUREAU N° REGISTRATION MARKS	SERIAL N°			TOTAL TIME	TIME SINCE OH				TOTAL TIME	TIME SINCE OH	
NOV. 02	9M-BOA	11211	AGUSTA	00.00	00.00	NEW	A2 1084	03.04. 2009	1623. 60	1623. 60	NEW	DUE FOR 1200.00 HRS. EXT 30HRS (1623.20 HRS) W/S. 0689/BOA
20.09. 2016.	9M-BOB	11212	AH200.	3169. 40.	1623,60	//	PLN C4 ASB					





