Summary of Arriel 2C Maintenance Manual No X 292 M1 450 2 Update No. 55: Dec 30/2023

			Applicability (YES /N/A)						
No.	Description	Task No. ASK No. / Spares Catalog Item	ENGINE M70-01		ENGINE M70-02		ENGINE M70-03		Remarks
			SN 24401	SN 24422	SN 24453	SN 24275	SN 24423	SN 24125	
	Addition of P/N 2292810970 for power turbine disc.	05-10-01-200-801	N/A	N/A					For info only. Not applicable due aircraft M70- 01 fitted: 1) Engine No 1 S/N 24401 fited with Power turbine disc P/N 2292810790 S/N 3481XG. 2) Engine No 2 S/N 24422 fited with Power turbine disc P/N 2292810790 S/N APL244TY.
1					N/A	N/A			For Info only. Not applicable due aircraft M70- 02 fitted: 1) Engine No 1 S/N 24453 fitted with Power turbine disc P/N 2292810790 S/N AP111547. 2) Engine No 2 S/N 24275 fitted with Power turbine disc P/N 2292810610 S/N AP308585.
							N/A	N/A	For Info only. Not applicable due aircraft M70- 03 fitted: 11 Engine No 1 S/N 24423 fitted with Power turbine disc P/N 229281.0610 S/N APJ261882. 2) Engine No 2 S/N 24125 fitted with Power turbine disc P/N 2292810310 S/N APJ124828.
	Harmonisation of the designation of the "Spectrometric oil analysis" task and modification of the minimum standards of the component.	05-20-10-201-817	N/A	N/A					1) For info only, 50 FH Spectrometric oil analysis not applicable due aircraft M70-01 fitted with Engine No 1 S/N 24401 is Post TU 100A & Post TU 145A. 2) For info only, Task 50 FH Spectrometric oil analysis is not applicable due aircraft M70-01 fitted with Engine No 2 S/N 24422 is Post TU 100A & Pre TU 145A.
2					N/A	N/A			For info only. 50 FH Spectrometric oil analysis not applicable due aircraft M70-02: Ji Engine No 1 S/N 24453 is Post TU 100A & Post TU 145A. 2) Engine No 2 S/N 24275 is Post TU 100A & Post TU 145A.
							N/A	N/A	For Info only. 50 FH Spectrometric oil analysis not applicable due aircraft M70-03: 1) Engine No 15/N 24423 is Post TU 100A & Post TU 145A. 2) Engine No 2 5/N 24125 is Post TU 100A & Post TU 145A
3	Update of blanks references and markers.	71-05-01-280-802	N/A	N/A	N/A	N/A	N/A	N/A	For info only.
4	Update of the installation procedure of the inlet cone on the module 02 compressor.	72-00-32-900-801	N/A	N/A	N/A	N/A	N/A	N/A	For info only.
5	Update of the inspection procedure of the Igniter plugs.	72-43-00-200-803	N/A	N/A	N/A	N/A	N/A	N/A	For info only.
6	Update of the installation procedure of the engine front support.	72-61-00-900-810	N/A	N/A	N/A	N/A	N/A	N/A	For info only.
7	Update of the removal/installation procedure of the seal on the breather cover.	72-61-00-900-811	N/A	N/A	N/A	N/A	N/A	N/A	For info only.
8	Update of the removal/installation procedure of the seal on the dynastart adapter.	72-61-00-900-812	N/A	N/A	N/A	N/A	N/A	N/A	For info only.
9	Update of the replacement procedure of the magnetic seal on the drive shaft.	72-61-20-950-801	N/A	N/A	N/A	N/A	N/A	N/A	For info only.
10	Creation of the electrical testing task for the P3 air pressure transmitter with the use of the ADT 760- MA-DL TEST KIT tool.	75-41-00-750-801	N/A	N/A	N/A	N/A	N/A	N/A	For info only.

List of tasks that have been subject to modification but without revision mark:										
	Description	Task No. ASK No. / Spares Catalog Item								
No.			ENGINE M70-01		ENGINE M70-02		ENGINE M70-03		Remarks	
			SN 24401	SN 24422	SN 24453	SN 24275	SN 24423	SN 24125		
1	-	00-00-00-APP-801-A01	N/A	N/A	N/A	N/A	N/A	N/A	For info only.	
2	Reference Task 71-02-07-280-803-A01 deleted	71-02-07-280-801-A01	N/A	N/A	N/A	N/A	N/A	N/A	For info only.	
3	DELETED	71-02-07-280-803-A01	N/A	N/A	N/A	N/A	N/A	N/A	For info only.	