

GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]
Suite 11-14, Helicopter Centre, Malaysia International Aerospace Co
Sultan Abdul Aziz Shah Airport, 47200 Subbang, Selangor, Malaysia.
Tel: +603 7734 7226 | Fax: +603 7734 7526
www.galaxyaerospace.my | enquiry@galaxyaerospace.my I nal Aerospace Centre,

WORKPACK

CLIENT/OWNER: APMM SUBANG AIR STATION SERIAL NO. HOURS LDG/CYCLE WORKPACK NO: M72-02-5376 SB NO. 139-616 NEW ISSUE - PART I AIRCRAFT TYPE:AW139 31315 WORK/INSP/DESC: **AIRCRAFT** REGISTRATION: M72-02 AERONET JOB NO.: 2024-5376 PCE-KB0740 #1 ENGINE: N/A N/A BASE/FACILITY: APMM, WMSA AJL REF NO.: #2 ENGINE: PCE-KB0732 N/A N/A DATE IN: OUT: SHEET: 1 OF NF/N2 NG/N1 Reason for raising: Raised by and date: Other requirements/information: SB NO. 139-616 NEW ISSUE ATA 53 - LOWER LH TAIL LONGERON INSPECTION AND CAMO; Nur Atira Najihah REPAIR ON PART I TO BE CARRIED OUT IN ACCORDANCE WITH SB NO. 139-616 NEW N/A binti Anuar ISSUE ACCOMPLISHMENT INSTRUCTIONS PART I 03/07/2024 DUE ON: 18.12.2024 List of scheduled inspection and all work carried out under this workpack including individual reference. Master Signature Schedule APP/STAMP/ DATE TOTAL NO. INSPECTION / WORK **WORKSHEET REF** NAME **SIGNATURE** COMPLETED STAFF ID M/H SB NO. 139-616 NEW ISSUE - ATA 53 LOWER 5376-001 1 LH TAIL LONGERON INSPECTION AND REPAIR ON PART I NAME FIRM DATE SIGN & APPROVAL PART 145 - AMO RELEASE STATEMENT THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND OEM PUBLICATION/ REVISION:..



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D] Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax: +603 7734 7526

WORKSHEET

CLIENT/OWNER: APMM SUBANG AIR STATION SERIAL NO. HOURS LDG/CYCLE WORKSHEET NO: 5376-001 SB NO. 139-616 NEW 31315 REFER WORKPACK **AIRCRAFT** WORK/INSP/DESC: AIRCRAFT TYPE: AW139 ISSUF - PART I M72-02 PCE-KB0740 WORKPACK REF: M72-02-5376 REFER WORKPACK #1 ENGINE: REGISTRATION: BASE/FACILITY: APMM, WMSA REFER WORKPACK AJL REF NO.: PCF-KB0732 #2 FNGINE: DATE IN: REFER WORKPACK OUT: REFER WORKPACK SHEET: 1 OF NF/N2 1 NG/N1 Reason for raising: Raised by and date: Other requirements/information: SB NO. 139-616 NEW ISSUE ATA 53 - LOWER LH TAIL LONGERON INSPECTION AND CAMO; Nur Atira Najihah REPAIR ON PART I TO BE CARRIED OUT IN ACCORDANCE WITH SB NO. 139-616 NEW binti Anuar N/A ISSUE ACCOMPLISHMENT INSTRUCTIONS PART I. 03/07/2024 DUE ON: 18.12.2024 * Eng. CRS Item Description Technician Date SB NO. 139-616 NEW ISSUE (PART I) - ATA 53 LOWER LH TAIL LONGERON INSPECTION AND REPAIR 1 PART I: FOR TAIL BOOM ASSEMBLIES INSTALLED ON AB139/AW139 HELICOPTERS: WITHIN AND NOT LATER THAN 6 MONTHS AFTER THE ISSUE OF THIS SERVICE BULLETIN. FOR TAIL BOOM ASSEMBLIES KEPT IN STOCK: BEFORE NEXT INSTALLATION. TO PERFORM A ONE-OFF CHECK FOR THE PRESENCE OF DRILL MARKS ON THE LONGERON. REFRERENCE: SB NO. 139-616 NEW ISSUE - ACCOMPLISHMENT INSTRUCTIONS ON PART I REMARKS: The work recorded above has been carried out in accordance with the AW139 Interactive Electronic Technical Publication (IETP), Air-vehicle Maintenance Planning Information (AMPI) - EASA and PT6C-67C Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS555SN Maintenance Manual, Airbus AS555SN Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arrius 1 A Maintenance Manual. П The work recorded above has been carried out in accordance with Super Lynx Compound Interactive Electronic Technical Publication (CIETP) and CTS800-40N Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS365N3 Maintenace Manual, Airbus AS365N3 Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arriel 2C Maintenance Manual The work recorded above has been carried out in accordance with the requirements of the Technical Airworthiness Management Manual (TAMM) for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.



GALAXY AEROSPACE (M) SDN, BHD, [1040262-D]

SALDAT AEROSPACE (m) SDIN. SRID.: [104u2c2-tr] Suite 11-14, Helicopter Centre, Malaysia International Aerospace C Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace..my | enquiry@galaxyaerospace.my nal Aerospace Centre. **PARTS REPORT**

SERIAL NO. HOURS LDG/CYCLE CLIENT/OWNER: APMM SUBANG AIR STATION 5377-001 WORKSHEET NO: SB NO. 139-616 NEW ISSUE - PART I 31315 REFER WORKPACK AIRCRAFT WORK/INSP/DESC: AIRCRAFT TYPE: AW139 PCE-KB0740 REFER WORKPACK WORKPACK REF: #1 ENGINE: M72-02-4953 REGISTRATION: M72-02 AJL REF NO: PCE-KB0732 REFER WORKPACK BASE/FACILITY: APMM, WMSA #2 ENGINE: DATE IN: REFER OUT: REFER WORKPACK SHEET: 1 NF/N2 NG/N1 Reason for raising: Raised by and date: Other requirements/information: SB NO. 139-616 NEW ISSUE ATA 53 - LOWER LH TAIL LONGERON INSPECTION AND CAMO; Nur Atira Najihah REPAIR ON PART I TO BE CARRIED OUT IN ACCORDANCE WITH SB NO. 139-616 NEW N/A binti Anuar ISSUE ACCOMPLISHMENT INSTRUCTIONS PART I. 03/07/2024 DUE ON: 18.12.2024 Serial Number Release Part No Lifed Item Information Item Description Qty Position Reason Reference Off On TSN/TSO/DUE/TIMEX NAME FIRM SIGN & APPROVAL DATE The work recorded above has been carried out in accordance with the AW139 Interactive Electronic Technical Publication (IETP), Air-vehicle Maintenance Planning Information (AMPI) - EASA and PT6C-67C Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS555SN Maintenance Manual, Airbus AS555SN Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arrius 1 A Maintenance Manual. The work recorded above has been carried out in accordance with Super Lynx Compound Interactive Electronic Technical Publication (CIETP) and CTS800-40N Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS365N3 Maintenace Manual, Airbus AS365N3 Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arriel 2C Maintenance Manual The work recorded above has been carried out in accordance with the requirements of the Technical Airworthiness Management Manual (TAMM)

for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.



Please send to the following address:		SERVICE BULLETIN COMPLIANCE FORM			Date: 19/06/2024			
LEONARDO S.p.A.								
CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988 Customer Name and Address:		Number: SB 139-616 - PART I Revision: Telephone:						
GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, SELANGOR DARUL EHSAN				603-7734 7226				
				Fax: 603-7734 7226 B.T. Compliance Date:				
Helicopter Model	S/N		Total Number		Total Hours	T.S.O.		
AW139	31315		1					
Remarks:								
Information:								
We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.								



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]
Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre,
Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.
Tel: +603 7734 7256 | Fax: +603 7734 7526
www.galaxyaerospace.my | enquiry@galaxyaerospace.my

WORKPACK

CLIENT/OWNER: APMM SUBANG AIR STATION SERIAL NO. HOURS LDG/CYCLE WORKPACK NO: M72-03-5377 SB NO. 139-616 NEW AIRCRAFT TYPE:AW139 31316 WORK/INSP/DESC: **AIRCRAFT** ISSUE - PART I REGISTRATION: M72-03 AERONET JOB NO.: 2024-5377 N/A #1 ENGINE: N/A N/A BASE/FACILITY: APMM, WMSA AJL REF NO.: #2 ENGINE: N/A N/A N/A DATE IN: OUT: SHEET: 1 OF NF/N2 NG/N1 Reason for raising: Raised by and date: Other requirements/information: SB NO. 139-616 NEW ISSUE ATA 53 - LOWER LH TAIL LONGERON INSPECTION AND CAMO; Nur Atira Najihah REPAIR ON PART I TO BE CARRIED OUT IN ACCORDANCE WITH SB NO. 139-616 NEW N/A binti Anuar ISSUE ACCOMPLISHMENT INSTRUCTIONS PART I 03/07/2024 DUE ON: 18.12.2024 List of scheduled inspection and all work carried out under this workpack including individual reference. Master Signature Schedule APP/STAMP/ DATE TOTAL NO. INSPECTION / WORK **WORKSHEET REF** NAME **SIGNATURE** COMPLETED STAFF ID M/H SB NO. 139-616 NEW ISSUE - ATA 53 LOWER 5377-001 1 LH TAIL LONGERON INSPECTION AND REPAIR ON PART I NAME FIRM DATE SIGN & APPROVAL PART 145 - AMO RELEASE STATEMENT THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND OEM PUBLICATION/ REVISION:..



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D] Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax: +603 7734 7526

WORKSHEET

CLIENT/OWNER: APMM SUBANG AIR STATION SERIAL NO. HOURS LDG/CYCLE WORKSHEET NO: 5377-001 SB NO. 139-616 NEW ISSUE - PART I 31316 REFER WORKPACK **AIRCRAFT** WORK/INSP/DESC: AIRCRAFT TYPE: AW139 N/A WORKPACK REF: M72-03-5377 M72-03 REFER WORKPACK #1 ENGINE: REGISTRATION: BASE/FACILITY: APMM, WMSA REFER WORKPACK AJL REF NO.: N/A #2 ENGINE: DATE IN: REFER WORKPACK OUT: REFER WORKPACK SHEET: 1 OF NF/N2 1 NG/N1 Reason for raising: Raised by and date: Other requirements/information: SB NO. 139-616 NEW ISSUE ATA 53 - LOWER LH TAIL LONGERON INSPECTION AND CAMO; Nur Atira Najihah REPAIR ON PART I TO BE CARRIED OUT IN ACCORDANCE WITH SB NO. 139-616 NEW binti Anuar ISSUE ACCOMPLISHMENT INSTRUCTIONS PART I. N/A 03/07/2024 DUF ON: 18 12 2024 * Eng. CRS Item Description Technician Date SB NO. 139-616 NEW ISSUE (PART I) ATA 53 - LOWER LH TAIL LONGERON INSPECTION AND REPAIR 1 PART I: FOR TAIL BOOM ASSEMBLIES INSTALLED ON AB139/AW139 HELICOPTERS: WITHIN AND NOT LATER THAN 6 MONTHS AFTER THE ISSUE OF THIS SERVICE BULLETIN. FOR TAIL BOOM ASSEMBLIES KEPT IN STOCK: BEFORE NEXT INSTALLATION. TO PERFORM A ONE-OFF CHECK FOR THE PRESENCE OF DRILL MARKS ON THE LONGERON. REFRERENCE: SB NO. 139-616 NEW ISSUE - ACCOMPLISHMENT INSTRUCTIONS ON PART I REMARKS: The work recorded above has been carried out in accordance with the AW139 Interactive Electronic Technical Publication (IETP), Air-vehicle Maintenance Planning Information (AMPI) - EASA and PT6C-67C Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS555SN Maintenance Manual, Airbus AS555SN Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arrius 1 A Maintenance Manual. П The work recorded above has been carried out in accordance with Super Lynx Compound Interactive Electronic Technical Publication (CIETP) and CTS800-40N Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS365N3 Maintenace Manual, Airbus AS365N3 Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arriel 2C Maintenance Manual The work recorded above has been carried out in accordance with the requirements of the Technical Airworthiness Management Manual (TAMM) for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.



GALAXY AEROSPACE (M) SDN, BHD, [1040262-D]

SALDAT AEROSPACE (m) SDIN. SRID.: [104u2c2-tr] Suite 11-14, Helicopter Centre, Malaysia International Aerospace C Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace..my | enquiry@galaxyaerospace.my nal Aerospace Centre. **PARTS REPORT**

CLIENT/OWNER: APMM SUBANG AIR STATION SERIAL NO. **HOURS** LDG/CYCLE 5377-001 WORKSHEET NO: SB NO. 139-616 NEW ISSUE - PART I 31316 REFER WORKPACK AIRCRAFT WORK/INSP/DESC: AIRCRAFT TYPE: AW139 N/A REFER WORKPACK WORKPACK REF: #1 ENGINE: M72-03-5377 REGISTRATION: M72-03 AJL REF NO: REFER WORKPACK N/A BASE/FACILITY: APMM, WMSA #2 ENGINE: DATE IN: REFER OUT: REFER WORKPACK 1 SHEET: NF/N2 NG/N1 Reason for raising: Raised by and date: Other requirements/information: SB NO. 139-616 NEW ISSUE ATA 53 - LOWER LH TAIL LONGERON INSPECTION AND CAMO; Nur Atira Najihah REPAIR ON PART I TO BE CARRIED OUT IN ACCORDANCE WITH SB NO. 139-616 NEW N/A binti Anuar ISSUE ACCOMPLISHMENT INSTRUCTIONS PART I. 03/07/2024 DUE ON: 18.12.2024 Serial Number Release Part No Lifed Item Information Item Description Qty Position Reason Reference Off On TSN/TSO/DUE/TIMEX NAME FIRM SIGN & APPROVAL DATE The work recorded above has been carried out in accordance with the AW139 Interactive Electronic Technical Publication (IETP), Air-vehicle Maintenance Planning Information (AMPI) - EASA and PT6C-67C Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS555SN Maintenance Manual, Airbus AS555SN Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arrius 1 A Maintenance Manual. The work recorded above has been carried out in accordance with Super Lynx Compound Interactive Electronic Technical Publication (CIETP) and CTS800-40N Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS365N3 Maintenace Manual, Airbus AS365N3 Airworthiness

The work recorded above has been carried out in accordance with the requirements of the Technical Airworthiness Management Manual (TAMM) for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

Limitations Section (ALS) and Master Servicing Manual (MSM) and Arriel 2C Maintenance Manual



Please send to the following address: LEONARDO S.p.A.		SERVIO	CE BULLE	Date: 19/06/2024			
LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988 Customer Name and Address: GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre Sultan Abdul Aziz Shah Airport, 47200 SELANGOR DARUL EHSAN					: 34 7226 34 7226		
Helicopter Model	S/N		Total N	lumber	Total Hours	T.S.O.	
AW139	31316			1			
Information: We request your cooperation in	n filling this form, in order t	o keep out sta	atistical data re	levant to aircra	aft configuration up-to-date.	The form should be filled in all	
	address or you can commu	unicate the app	plication also v	ria Technical E	Bulletin Application Communi	The form should be filled in all ication Section placed in	